





report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-4 ISG
Colour	Red
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-13

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-25
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #7	2024-01-08 17:36
MOT test number	764076577694
Result	✓ Passed
Next expiry date	2025-01-25
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm and V (e))	Wearing on Inner Edge (5.2.3

MOT #6	2024-01-08 11:02
MOT test number	106309419133
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm and Wearing on (e))	n Inner Edge (5.2.3
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Lipped and Worn (1.1.14 (a) (ii))	
Fail Brake performance unable to be tested Due to Rear Brake Condition (1.2.1 (g))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Li (1.1.14 (a) (ii))	ipped and Worn

MOT #5	2023-01-11 13:58
MOT test number	886329107550
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Emissions too clean

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number
990807003644

Result
Advice Stone chips in windscreen

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Spare wheel under car not secured tight fully

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

Result

Advice Plastic under tray fitted to under side of vehicle in places

2021-01-26 15:01

140585432792

✓ Passed

 MOT #1
 2020-01-08 11:37

 MOT test number
 882241722000

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report the current and the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have this KIA? How many owners did the current and previous owner(s) have the current and the current an</u>	

THE STATE OF THE S	

	More info >
<u></u>	
Plate changes	
See in this check if this KIA had different number plates.	
See in this check if this KiA had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-19
Last registration	2024-01-08
Complete history	See info



Registration #1	2017-01-19	29 mi
Registration #2	2020-01-08	58.665 mi
Registration #3	2021-01-26	60.828 mi
Registration #4	2022-01-10	63.468 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11




Car features

50225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1685 mm
Length	4780 mm
Wheel base	2780 mm
Kerb weight	1885 kg
Max. allowed weight	2620 kg

Additional information

Fuel tank capacity	71
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles 2

Engine number D4HBGH270812