



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	Blue
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	109 Nm at 3.600 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-05
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-10
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	43
Total items failed	26

MOT #17	2023-10-11 09:57
MOT test number	672193592369
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Some damage to o/s/f outer wheel rim

MOT #16	2023-10-03 14:46
MOT test number	746854411998
Result	✗ Failed
Advice	Some damage to o/s/f outer wheel rim
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))
Fail	Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #15	2022-10-06 12:00
MOT test number	616267506814
Result	✓ Passed
Advice	O/s/r tyre wearing on outer edge

MOT #14	2022-09-23 12:51
MOT test number	222787839440
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Exhaust shield missing where fitted as original equipment creating a risk of fire by fuel tank (6.1.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm inner edge (5.2.3 (e))
Fail	Exhaust system insecure (6.1.2 (a))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	O/s/r tyre wearing on outer edge

**MOT #13**

2021-09-10 17:34

**MOT test number**

183644371164

**Result**

✓ Passed

**Advice**

Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2020-09-03 12:04

**MOT test number**

980048122598

**Result**

✓ Passed

**Advice**

Covers fitted obstructing view

**Advice**

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice**

Both rear axle bushes deteriorated

**Advice**

Play in steering rack inner joint(s)

**MOT #11**

2020-09-03 08:45

**MOT test number**

934937951422

**Result**

✗ Failed

**Advice**

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice**

Covers fitted obstructing view

**Advice**

Play in steering rack inner joint(s)

**Fail**

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Both rear axle bushes deteriorated

**Fail**

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10**

2019-05-09 15:23

**MOT test number**

845932765294

**Result**

✓ Passed

- Advice** Both rear axle bushes deteriorated with slight play
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Covers fitted obstructing view
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #9**

2019-05-08 09:52

**MOT test number**

720414645692

**Result**

✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Front Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Advice** Covers fitted obstructing view
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Both rear axle bushes deteriorated with slight play

**MOT #8**

2018-05-08 15:47

**MOT test number**

440665429361

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit inner edge 0.0mm (4.1.E.1)**Advice** Items removed from driver's view prior to test**Advice** Covers fitted obstructing view**Advice** Both rear axle bushes deteriorated with slight play**Advice** Steering column universal joint has slight play (2.1.5)**MOT #7**

2018-05-08 09:08

**MOT test number**

537811550173

**Result**

✗ Failed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Steering column universal joint has slight play (2.1.5)**Advice** Items removed from driver's view prior to test**Advice** Both rear axle bushes deteriorated with slight play**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)**Advice** Covers fitted obstructing view**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit inner edge 0.0mm (4.1.E.1)



<b>MOT #6</b>	2017-04-29 11:50
---------------	------------------

<b>MOT test number</b>	869709250376
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #5</b>	2016-04-23 10:16
---------------	------------------

<b>MOT test number</b>	841885772709
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2015-05-22 17:16
---------------	------------------

<b>MOT test number</b>	857642245160
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-03-10 10:22
---------------	------------------

<b>MOT test number</b>	585159265086
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-03-25 11:10
---------------	------------------

<b>MOT test number</b>	336334784094
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2013-03-18 10:44
---------------	------------------

<b>MOT test number</b>	136447273463
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
10 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	10 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-01
Last registration	2023-10-11
Complete history	<a href="#">See info</a>



Registration #1	2010-04-01	18 mi
Registration #2	2013-03-18	19.832 mi
Registration #3	2014-03-25	22.523 mi
Registration #4	2015-03-10	25.346 mi
Registration #5	2015-05-22	25.501 mi
Registration #6	2016-04-23	35.927 mi
Registration #7	2017-04-29	47.893 mi
Registration #8	2018-05-08	59.512 mi
Registration #9	2018-05-08	59.512 mi
Registration #10	2019-05-08	70.651 mi
Registration #11	2019-05-08	70.651 mi
Registration #12	2019-05-08	70.651 mi
Registration #13	2019-05-08	70.651 mi
Registration #14	2019-05-08	70.651 mi
Registration #15	2019-05-08	70.651 mi
Registration #16	2019-05-08	70.651 mi
Registration #17	2019-05-08	70.651 mi
Registration #18	2019-05-08	70.651 mi
Registration #19	2019-05-08	70.651 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1098 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

**Engine number**

9K62960