



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Red
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-15
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #15	2023-06-12 08:10
MOT test number	865207297921
Result	✓ Passed
Next expiry date	2024-06-17

MOT #14	2023-06-12 08:10
MOT test number	296059218712
Result	✗ Failed
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #13	2022-06-15 10:25
MOT test number	126247842129
Result	✓ Passed
Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #12	2021-06-18 15:52
MOT test number	683660659575
Result	✓ Passed

**MOT #11** 2020-10-27 09:41**MOT test number** 487787370513**Result** ✓ Passed**MOT #10** 2019-04-17 08:25**MOT test number** 772581790701**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-04-17 08:25**MOT test number** 273004605605**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2018-04-19 12:21**MOT test number** 423935326302**Result** ✓ Passed**MOT #7** 2017-04-28 13:16**MOT test number** 631138029322**Result** ✓ Passed

**MOT #6** 2016-08-18 15:10**MOT test number** 906313205229**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Valve stem slightly damaged (4.1.D.1e)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Valve stem slightly damaged (4.1.D.1e)

MOT #5 2016-08-18 08:59**MOT test number** 177450583897**Result** ✗ Failed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Valve stem slightly damaged (4.1.D.1e)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Valve stem slightly damaged (4.1.D.1e)

MOT #4 2015-08-24 08:35**MOT test number** 786102234203**Result** ✓ Passed

**MOT #3** 2014-09-29 10:27**MOT test number** 845792774267**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2013-09-25 15:18**MOT test number** 646468263258**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-10-01 09:36**MOT test number** 417915372252**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
17 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	17 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	HW59GYY
Plate since	2019-03-29
Current registration	HW59GYY
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-08
Last registration	2023-06-12
Complete history	See info



Registration #1	2009-10-08	18 mi
Registration #2	2012-10-01	20.316 mi
Registration #3	2013-09-25	24.221 mi
Registration #4	2014-09-29	31.428 mi
Registration #5	2015-08-24	37.845 mi
Registration #6	2016-08-18	45.539 mi
Registration #7	2016-08-18	45.539 mi
Registration #8	2017-04-28	51.413 mi
Registration #9	2018-04-19	54.768 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607