



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Grey
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	43
Total items failed	36

MOT #21 2024-03-21 17:39

MOT test number 825986368409

Result ✓ Passed

Next expiry date 2025-03-23

- Minor** Offside Obligatory mirror slightly damaged Strong advise (3.3 (b) (i))
- Advice** Steering feels slightly stiff
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Engine stabiliser bar loose/ 1x bolt sheared /strong advise.

MOT #20 2024-03-21 12:01

MOT test number 816066511316

Result ✗ Failed

- Advice** Steering feels slightly stiff
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Obligatory mirror slightly damaged Strong advise (3.3 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #19**

2023-03-24 13:23

MOT test number

101712779186

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18

2023-03-22 08:40

MOT test number

671220560153

Result

✗ Failed

- Fail** Nearside Rear Inner Road wheel badly distorted (5.2.2 (c) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Exhaust has a major leak of exhaust gases front pipe flexi (6.1.2 (a))
- Minor** Nearside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))
- Advice** Offside Front cv boot wet but not split
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Direction indicator not working mirror repeater (4.4.1 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #17**

2022-03-18 11:12

MOT test number

252502940405

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Borderline (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Borderline (5.2.3 (e))

MOT #16

2022-03-14 12:50

MOT test number

155477618479

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Borderline (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Borderline (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15

2021-03-15 13:18

MOT test number

783365046222

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14** 2020-08-28 14:29**MOT test number** 725132048963**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-03-14 10:59**MOT test number** 252694272665**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-03-14 10:58**MOT test number** 277465053348**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-02-28 15:00**MOT test number** 607495592612**Result** ✓ Passed**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside mirror glass

**MOT #10** 2017-01-26 09:19**MOT test number** 501549775629**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #9** 2017-01-25 13:18**MOT test number** 570170319632**Result** ✗ Failed**Fail** Offside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #8** 2015-10-15 14:50**MOT test number** 547487790388**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #7** 2015-10-03 08:14**MOT test number** 989156535146**Result** ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Registration plate lamp not fitted (1.1.C.1b)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #6 2013-12-30 06:21**MOT test number** 915674663360**Result** ✓ Passed**MOT #5** 2013-12-30 06:21**MOT test number** 975684863323**Result** ✗ Failed

- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #4** 2013-12-06 17:57**MOT test number** 429720543309**Result** ✗ Failed**Fail** Offside Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)**Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2012-10-16 17:47**MOT test number** 887770392227**Result** ✓ Passed**MOT #2** 2011-09-12 12:40**MOT test number** 399995651217**Result** ✓ Passed**MOT #1** 2011-09-06 17:51**MOT test number** 376289341478**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Inner Front Body or chassis has an inadequate repair, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Horn not working (1.6.2a)**Fail** Nearside Front Anti-roll bar linkage inappropriately repaired (2.4.A.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KV58LVN
Plate since	2024-03-29
Current registration	 KV58LVN
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-01
Last registration	2024-03-21
Complete history	See info



Registration #1	2008-09-01	10 mi
Registration #2	2011-09-06	16.309 mi
Registration #3	2011-09-12	16.309 mi
Registration #4	2012-10-16	16 mi
Registration #5	2013-12-06	19.445 mi
Registration #6	2013-12-30	19.837 mi
Registration #7	2015-10-03	24.224 mi
Registration #8	2015-10-15	24.230 mi
Registration #9	2017-01-25	25.703 mi
Registration #10	2017-01-26	25.703 mi
Registration #11	2018-02-28	27.642 mi
Registration #12	2019-03-20	28.277 mi
Registration #13	2019-03-20	28.277 mi
Registration #14	2019-03-20	28.277 mi
Registration #15	2019-03-20	28.277 mi
Registration #16	2019-03-20	28.277 mi
Registration #17	2019-03-20	28.277 mi
Registration #18	2019-03-20	28.277 mi
Registration #19	2019-03-20	28.277 mi
Registration #20	2019-03-20	28.277 mi
Registration #21	2019-03-20	28.277 mi
Registration #22	2019-03-20	28.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD524379