





### General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Blue
Year of manufacture	2010
Top speed	155 mph
Gearbox	7 speed automatic

# Engine & fuel consumption

184 BHP	0 < 101 A
250 Nm at 2.800 rpm	101 - 120 B
1.796 cc	121 - 140 P
4	141 - 165
Petrol	166 - 185
23.9 mpg	186 - 225
45.6 mpg	225+
34.5 mpg	
196 g/km	
J	
	250 Nm at 2.800 rpm 1.796 cc 4 Petrol 23.9 mpg 45.6 mpg 34.5 mpg





Internet history	
Entry 1	
Date	2021-09-25
Pictures	0
Listing price	View report

source: cargurus.co.uk



# MOT history

MOT expiry date	2025-04-05
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #13	2024-03-27 12:11
MOT test number	587699989965
Result	✓ Passed
Next expiry date 2025-04-05	
Advice Offside Front Lower Suspension arm ball joint has slight play rearmost ball joint/arm. (5.3.4 (a) (i))	
<b>Advice</b> Offside Rear Inner Brake pipe corroded, covered in grease or other material front to rear pipe corroded above axle. (1.1.11 (c))	

MOT #12	2024-03-27 12:11	
MOT test number	416275082418	
Result	× Failed	
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Offside Front Lower Suspension arm ball joint has slight play rearmost ball joint/arm. (5.3.4 (a) (i))		
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Offside Rear Inner Brake pipe corroded, covered in grease or other material front to rear pipe corroded above axle. (1.1.11 (c))		

MOT #11	2023-04-03 13:05
MOT test number	261970580712
Result	✓ Passed



<b>GY60BN</b>	Κ
report date: 2024-0	3-29

MOT #10		2022-04-06 11:00
MOT test	number	109963010094
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9		2021-06-25 12:23
MOT test	number	674662241466
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge attention soon. (5.2.3	(e))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #8		2020-07-01 15:04
MOT test	number	312604140830
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured attention soon. (4.4.3 (a))	
Advice	Offside Rear Direction indicator slightly discoloured attention soon. (4.4.3 (a))	

MOT #7	2019-07-08 08:32
MOT test number	574780726626
Result	✓ Passed



GY60BNK report date: 2024-03-29

MOT #6	2018-09-22 10:56
MOT test number	713263723031
Result	✓ Passed
MOT #5	2017-09-29 08:01
MOT test number	708172769638
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Nail in tyre	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-09-16 12:55
MOT test number	630117505756
Result	✓ Passed

МОТ #3	2015-09-25 13:40
MOT test number	368175879767
Result	✓ Passed

MOT #2	2014-08-29 16:09
MOT test number	278311344254
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2013-09-07 09:57
MOT test number	786190253270
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	



GY60BNK report date: 2024-03-29

Tax & MOT check

X Untaxed	√ МОТ
Tax expired: 1 March 2024	<b>Expires:</b> 5 April 2025
Tax status	Expired at 1 March 2024
Days left	60 days too late
MOT expiry date	5 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

********	
***********	
********	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



GY60BNK report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-25
Last registration	2024-03-27
Complete history	See info



Registration #1	2010-09-25	16 mi
Registration #2	2013-09-07	19.494 mi
Registration #3	2014-08-29	25.205 mi
Registration #4	2015-09-25	31.585 mi
Registration #5	2016-09-16	37.214 mi
Registration #6	2017-09-29	43.211 mi
Registration #7	2018-09-22	48.674 mi
Registration #8	2019-07-08	52.718 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi

More info  $\rightarrow$ 



## Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

## Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431331085