



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	Black
Year of manufacture	2017
Top speed	147 mph
0 - 100 km/h	6.7 seconds
0 - 60 mph	6.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 5

Date	2021-12-09
Pictures	20
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



Entry 4

Date	2021-12-09
Pictures	0
Listing price	View report

source: [heyicar.co.uk](https://www.heyicar.co.uk)

Entry 3


Date	2021-12-08
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2


Date	2021-11-10
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-10-23
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-30
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	23
Total items failed	0

MOT #7 2023-11-28 10:23

MOT test number 892386637985

Result ✓ Passed

Next expiry date 2024-11-30

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2022-12-01 09:59

MOT test number 457544966565

Result ✓ Passed

MOT #5 2021-11-01 11:42

MOT test number 159282636646

Result ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake disc worn, but not excessively both rear (1.1.14 (a) (i))

**MOT #4** 2021-11-01 09:32**MOT test number** 784394212950**Result** ✗ Failed**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake disc worn, but not excessively both rear (1.1.14 (a) (i))**MOT #3** 2021-02-19 16:07**MOT test number** 803655983623**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2** 2021-02-19 13:09**MOT test number** 112034458084**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #1** 2020-02-21 11:25**MOT test number** 316776285919**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FY66SZX
Plate since	2024-03-29
Current registration	 FY66SZX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2017-02-27
Last registration	2023-11-28
Complete history	See info



Registration #1	2017-02-27	15 mi
Registration #2	2020-02-21	25.146 mi
Registration #3	2021-02-19	29.596 mi
Registration #4	2021-02-19	29.596 mi
Registration #5	2021-11-01	34.774 mi
Registration #6	2021-11-01	34.774 mi
Registration #7	2021-11-01	34.774 mi
Registration #8	2021-11-01	34.774 mi
Registration #9	2021-11-01	34.774 mi
Registration #10	2021-11-01	34.774 mi
Registration #11	2021-11-01	34.774 mi
Registration #12	2021-11-01	34.774 mi
Registration #13	2021-11-01	34.774 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	DAJA037556