





report date: 2024-03-28

General information

| Make | JAGUAR |
|---------------------|-------------------|
| Model | XF D V6 S |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 155 mph |
| 0 - 60 mph | 6.1 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 296 BHP |
|-------------------------|---------------------|
| Max. torque | 700 Nm at 2.000 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 154 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



OY18ULS report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-08

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

Entry 1

Date 2021-10-07

Pictures 3

Listing price <u>View report</u>



WHY NOT TAKE
ADVANTAGE OF
OUR LIVE VIDEO &
CLICK AND COLLECT
OR DELIVERY SERVICE



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-05-19 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 2 |

| MOT #4 | | 2023-04-27 15:35 |
|-----------|---|------------------|
| MOT test | number | 980819151895 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-05-19 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Engine cover,under tray & plastic sill covers fitted | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | | 2022-05-20 11:54 |
|----------|--|------------------|
| MOT test | number | 112001323887 |
| Result | | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1. | .14 (a) (ii)) |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2022-05-17 10:57 **MOT test number** 759076250430 Result × Failed Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii)) Advice **Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner Edge (5.2.3 (e)) Fail Offside Front Road wheel fractured (5.2.2 (a)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

| MOT #1 | 2021-03-12 14:4 |
|-----------------|---|
| MOT test | number 13760243056 |
| Result | ✓ Passe |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Items removed from driver's view prior to test |
| Advice (d) (i)) | Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords wall slight (5.2.3 |
| Advice | Front and rear inner pads getting low |

CarCheck.co.uk page 4/11



OY18ULS report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 32 |
| MOT expiry date | 19 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| - | |
|--|--------------|
| Vehicle class | 49 |
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



OY18ULS report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
|---|-------------|
| | |
| | |
| *********** | |
| ********** | |
| *************************************** | |
| *********** | |
| | More info > |
| Plate changes | |
| See in this check if this JAGUAR had different number plates. | |
| Number of plates | |
| Current registration | NE NE |
| Plate since | |
| Current registration | AR AR |
| Plate since | PRO-00-0 |
| | More info > |

CarCheck.co.uk page 8/11



OY18ULS report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-03-14 |
| Last registration | 2023-04-27 |
| Complete history | See info |



| Registration #1 | 2018-03-14 | 14 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-03-12 | 26.824 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.177 es |
| Registration #6 | | 11.177 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 84% |
| Pedestrian | 80% |
| Safety systems | 83% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| Width | 2091 mm |
|---------------------|---------|
| Height | 1496 mm |
| Length | 4955 mm |
| Wheel base | 2960 mm |
| Max. allowed weight | 2390 kg |

Additional information

| Fuel tank capacity | 66 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1224471306DT |

CarCheck.co.uk page 11/11