



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Blue
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-10-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	8

## MOT #15 2023-10-05 12:12

MOT test number 410577947440

Result ✓ Passed

Next expiry date 2024-10-26

- Advice** Nearside Front Brake drum worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake drum worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

## MOT #14 2022-10-25 11:17

MOT test number 382857157558

Result ✓ Passed

## MOT #13 2021-10-08 14:05

MOT test number 899669224627

Result ✓ Passed

**MOT #12** 2021-10-08 14:05**MOT test number** 480855073899**Result** ✗ Failed

**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2020-10-27 08:56**MOT test number** 944650028729**Result** ✓ Passed**MOT #10** 2020-10-27 08:56**MOT test number** 123016189892**Result** ✗ Failed

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**MOT #9** 2019-12-19 11:08**MOT test number** 700432809670**Result** ✓ Passed

**Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))

**MOT #8** 2019-01-03 12:02**MOT test number** 381178487335**Result** ✓ Passed

**MOT #7**

2018-12-29 09:43

**MOT test number**

677718388366

**Result**

✗ Failed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #6**

2017-12-20 10:01

**MOT test number**

968305506631

**Result**

✓ Passed

**MOT #5**

2016-12-22 10:15

**MOT test number**

821466462418

**Result**

✓ Passed

**MOT #4**

2015-12-22 13:06

**MOT test number**

354768279508

**Result**

✓ Passed

**Advice** Offside front tyre wearing edge**Advice** Offside handbrake slight low effort**Advice** Both rear tyres bald edges**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear seats removed at time of test



MOT #3 2014-12-29 14:36

MOT test number 968683164353

Result ✓ Passed

- Notice** Coolant leak
- Notice** Offside rear tyre wearing edge
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside rear tyre wearing edge

MOT #2 2013-12-30 14:39

MOT test number 468214263369

Result ✓ Passed

MOT #1 2012-11-12 14:40

MOT test number 606727512343

Result ✓ Passed

- Notice** Damage to rear registration plate digit still visable



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-30
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2009-12-30	7 mi
Registration #2	2012-11-12	16.137 mi
Registration #3	2013-12-30	24.652 mi
Registration #4	2014-12-29	32.081 mi
Registration #5	2015-12-22	38.964 mi
Registration #6	2016-12-22	45.122 mi
Registration #7	2017-12-20	48.848 mi
Registration #8	2018-12-29	51.996 mi
Registration #9	2019-01-03	52.002 mi
Registration #10	2019-01-03	52.002 mi
Registration #11	2019-01-03	52.002 mi
Registration #12	2019-01-03	52.002 mi
Registration #13	2019-01-03	52.002 mi
Registration #14	2019-01-03	52.002 mi
Registration #15	2019-01-03	52.002 mi
Registration #16	2019-01-03	52.002 mi
Registration #17	2019-01-03	52.002 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C57284