



UK

BJ08FWB

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Grey
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



MOT history

MOT #18	2022-01-21 15:58
MOT test number	330746528233
Result	✓ Passed
Next expiry date	2023-01-20
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17	2020-12-11 15:30
MOT test number	480065917523
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #16	2019-06-15 13:25
MOT test number	220979953859
Result	✓ Passed

MOT #15	2019-06-15 13:25
MOT test number	130726515729
Result	✗ Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a))
Pass with rectification	Nearside Headlamp aim too high and too far to the left. (4.1.2 (a))

MOT #14	2018-06-22 17:59
MOT test number	587232978777
Result	✓ Passed

**MOT #13** 2017-06-24 10:10**MOT test number** 669721759125**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Front Inner Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #12 2017-06-24 08:18**MOT test number** 883239348916**Result** ✗ Failed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Front Inner Suspension arm has slight play in a pin/bush (2.4.G.2)
- Fail** Central Rear Seat belt flexible stalk damaged likely to lead to failure under load (5.2.4a)

MOT #11 2016-06-24 12:41**MOT test number** 866618783197**Result** ✓ Passed

**MOT #10**

2016-06-24 09:19

MOT test number

999521945555

Result**✗ Failed****Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Headlamp aim too low (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**MOT #9**

2015-06-25 12:48

MOT test number

578116875183

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2015-06-24 14:21**MOT test number** 619905375106**Result** ✗ Failed**Fail** Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in offside rear tyre**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-06-25 13:00**MOT test number** 285716974177**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #6** 2014-06-24 11:49**MOT test number** 556725074124**Result** ✗ Failed**Notice** Nail in offside rear tyre**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2013-11-04 14:24**MOT test number** 606138903396**Result** ✓ Passed**Notice** O/s/f brake pads are low**Notice** Rear brake pads worn low**Notice** Front brake disc worn low**MOT #4** 2013-11-02 16:59**MOT test number** 419906403372**Result** ✗ Failed**Notice** Rear brake pads worn low**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Front brake disc worn low**Notice** O/s/f brake pads are low**MOT #3** 2012-05-01 14:39**MOT test number** 426882622154**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Nearside/offside front tyre treads wearing low on edges.**Notice** Nail in nearside rear tyre**Notice** Nearside rear tyre perishing.**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #2** 2011-04-01 12:33**MOT test number** 758291591007**Result** ✓ Passed



MOT #1	2011-03-31 14:11
MOT test number	716620091017
Result	✗ Failed
Fail	Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)
Fail	Nearside Outer Rear Seat belt locking mechanism does not secure or release (5.2.5a)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BJ08FWB
Plate since	2024-03-29
Current registration	 BJ08FWB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-04
Last registration	2022-01-21
Complete history	See info



Registration #1	2008-04-04	16 mi
Registration #2	2011-03-31	12.564 mi
Registration #3	2011-04-01	12.564 mi
Registration #4	2012-05-01	23.579 mi
Registration #5	2013-11-02	39.603 mi
Registration #6	2013-11-04	39.603 mi
Registration #7	2014-06-24	45.890 mi
Registration #8	2014-06-25	45.890 mi
Registration #9	2015-06-24	59.060 mi
Registration #10	2015-06-25	59.060 mi
Registration #11	2015-06-25	59.060 mi
Registration #12	2015-06-25	59.060 mi
Registration #13	2015-06-25	59.060 mi
Registration #14	2015-06-25	59.060 mi
Registration #15	2015-06-25	59.060 mi
Registration #16	2015-06-25	59.060 mi
Registration #17	2015-06-25	59.060 mi
Registration #18	2015-06-25	59.060 mi
Registration #19	2015-06-25	59.060 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658