





report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Black
Year of manufacture	2009
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

Date 2021-10-13

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-09-19
------	------------


Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-07-30

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-23
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	14
Total items failed	9

MOT #19	2023-08-24 08:43
MOT test number	215331654105
Result	✓ Passed
Next expiry date	2024-08-23

MOT #18	2022-10-13 13:45
MOT test number	839070282397
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge x3 both rear and o/s front (5.2.3 (e))	

MOT #17	2022-10-12 08:46
MOT test number	169758332222
Result	× Failed
Advice Tyre worn close to legal limit/worn on edge x3 both rear and o/s front (5.2.3 (e)) Fail Offside Rear fog lamp not working bulb holder rotten (4.5.1 (a) (ii))	

MOT #16	2021-10-13 09:25
MOT test number	402445907876
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15 2021-10-13 09:25

MOT test number 775815320741

Result X Failed

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #14 2020-11-30 17:08

MOT test number 538863747564

Result
✓ Passed

MOT #13 2020-11-30 11:21

MOT test number 864328495968

Result X Failed

Fail

Offside Front Inner Steering linkage ball joint has excessive play rack joint (2.1.3 (b) (i))

MOT #12 2019-09-17 10:41

MOT test number 247199783129

Result \(\sqrt{Passed} \)

Advice

Offside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Minor (i))

Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g)

MOT #11 2018-09-10 11:25

MOT test number 575567092402

Result ✓ Passed

MOT #10 2017-09-20 14:05

MOT test number 869391067289

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

 MOT #9
 2017-09-20 10:13

 MOT test number
 867253215216

Result × Failed

Fail Nearside Steering rack gaiter split (2.2.D.2d)

MOT #8 2016-09-21 12:45

MOT test number 965265322611

Result ✓ Passed

MOT #7 2015-09-29 10:26

MOT test number 235431130190

Result
✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake discs slightly worn

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-09-29 10:26

MOT test number 435496782264

Result X Failed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Front brake discs slightly worn

MOT #5 2014-10-04 11:31

MOT test number 397547174234

Result

Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4

MOT test number

Result

Notice Offside rear tyre starting to distort on tread

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT test number
767025753219

Result
Notice Offside rear tyre starting to distort on tread

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Pass with rectification Front registration plate deteriorated (6.3.1d)

MOT #2 2012-09-27 15:23 **MOT** test number 848481772205 Result ✓ Passed **MOT #1** 2012-09-27 12:08 **MOT** test number 128501472257 Result × Failed Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$^{\prime}$	wn	Δr	h	ic	t٥	'n

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if		e?

2000000		

	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NY	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-09-29
Last registration	2023-08-24
Complete history	See info



2009-09-29	16 mi
	10 1111
2012-09-27	22.790 mi
2012-09-27	22.790 mi
2013-09-12	31.277 mi
2014-10-04	38.687 mi
2015-09-29	46.530 mi
2015-09-29	46.530 mi
2016-09-21	52.720 mi
2017-09-20	58.810 mi
2017-09-20	58.810 mi
2018-09-10	63.531 mi
	11.177 es
	11.777 es
	11.177 es
	11.777 es
	11.777 es
	11.177 mi
	11.177 es
	11.777 es
	2012-09-27 2013-09-12 2014-10-04 2015-09-29 2015-09-29 2016-09-21 2017-09-20 2017-09-20 2018-09-10

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1950 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 9G69435