





report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 BUSINESS EDITION
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-11

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



YP63URM report date: 2024-03-28

MOT history

MOT expiry date	2025-03-08
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #9		2024-03-07 17:20
MOT test	number	960531343093
Result		✓ Passed
Next expi	ry date	2025-03-08
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))	

MOT #8	2023-03-04 11:40
MOT test number	547999227127
Result	✓ Passed
MOT #7	2022-03-07 16:23
MOT test number	731079828760

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2021-03-09 09:08

MOT test number 494872623236

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge wear and outer wall damaged slightly (5.2.3 (e))

MOT #5 2020-03-07 13:04

MOT test number 175459739019

Advice Rear Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))

MOT #4 2020-03-04 14:57

MOT test number 302664083820

Result X Failed

Advice Rear Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))

MAJOR Offside Parking brake inoperative on one side (1.4.1 (a))

MAJOR Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #3 2019-01-30 09:20

MOT test number 216547226764

Result

Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Electronic parking brake defective but can be satisfactorily operated intermittent parking brake not fully released displayed on dashboard (1.1.6 (d))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2		2018-01-04 17:06
MOT test	number	374500816178
Result		✓ Passed
Advice	O/s/f disc slightly pitted/scored	
Advice	Brake pad(s) wearing thin (3.5.1g)	
Advice	Nail in o/s/f tyre	

MOT #1	2016-12-20 11:02
MOT test number	493367376161
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK AND
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-12-20
Last registration	2024-03-07
Complete history	See info



Registration #1	2013-12-20	16 mi
Registration #2	2016-12-20	41.324 mi
Registration #3	2018-01-04	48.377 mi
Registration #4	2020-03-04	65.198 mi
Registration #5	2020-03-07	65.210 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1516 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2
Engine number 2675170