



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Beige
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.4 mpg
CO2 emission	221 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-11
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-23
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	54
Total items failed	9

MOT #22	2023-05-24 11:21
MOT test number	174409647907
Result	✓ Passed
Next expiry date	2024-05-23
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #21	2023-05-24 11:21
MOT test number	840586828311
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #20**

2022-05-19 15:29

MOT test number

744857735233

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19**

2022-05-19 15:29

MOT test number

815716507464

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #18**

2021-05-17 09:19

MOT test number

296865083696

Result

✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #17**

2020-05-20 15:07

MOT test number

862016504037

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))**Advice** Nearside Rear tyre perished**MOT #16**

2020-01-31 14:56

MOT test number

677578806330

Result

✗ Failed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Offside Rear Tyre perished**MOT #15**

2018-07-05 15:08

MOT test number

904437873966

Result

✓ Passed

Advice Offside Rear tyre badly perished**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #14**

2017-06-30 14:57

MOT test number

385311357099

Result

✓ Passed

Advice Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Front Upper Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

**MOT #13** 2017-06-29 10:33**MOT test number** 221874393188**Result** ✗ Failed**Advice** Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Nearside Front Inner Drive shaft which forms part of the suspension coupling gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.4.G.4e)**Advice** Offside Front Upper Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**MOT #12** 2016-06-20 12:40**MOT test number** 994087788152**Result** ✓ Passed**MOT #11** 2016-06-20 09:48**MOT test number** 194963061474**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #10**

2015-06-08 14:05

MOT test number

569969355113

Result

✓ Passed

- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front suspension has slight deterioration of the bonding between metal and flexible material of an upper support bearing (2.5.B.3a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Both rear tyres deteriorating and cracking within treads
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Centre exshaust mounting broken but still supporting

MOT #9

2014-06-20 13:09

MOT test number

789531274174

Result

✓ Passed

- Notice** N/S/F inner cv gator perishing and cracked
- Notice** Front top strut mount bearing's slightly noisy
- Notice** Front brake disc's poor
- Notice** Slight lift in both front top strut mount bushes
- Notice** Rear brakes 15% balance
- Notice** Front brake pads getting low
- Notice** Both rear tyres perishing and badly cracked

**MOT #8** 2013-06-22 12:36**MOT test number** 667723973196**Result** ✓ Passed**MOT #7** 2013-01-30 17:02**MOT test number** 635080433042**Result** ✓ Passed**MOT #6** 2012-01-06 11:25**MOT test number** 436816902090**Result** ✓ Passed**Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Notice** Airbag light is on**Advice** Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #5** 2011-01-05 14:18**MOT test number** 118315301452**Result** ✓ Passed**Notice** Front tyres wearing low .**MOT #4** 2009-10-29 11:35**MOT test number** 413362409332**Result** ✓ Passed



MOT #3	2008-10-28 11:29
MOT test number	890822108387
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2007-11-01 11:48
MOT test number	160205507365
Result	✓ Passed
Notice	Rear brake pads getting low
Notice	Nearside rear tyre appears under-inflated

MOT #1	2006-09-04 14:39
MOT test number	660897846282
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DU53CXE
Plate since	2019-06-29
Current registration	 DU53CXE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-10-01
Last registration	2023-05-24
Complete history	See info



Registration #1	2003-10-01	15 mi
Registration #2	2006-09-04	22.639 mi
Registration #3	2007-11-01	31.402 mi
Registration #4	2008-10-28	41.028 mi
Registration #5	2009-10-29	51.251 mi
Registration #6	2011-01-05	60.841 mi
Registration #7	2012-01-06	66.582 mi
Registration #8	2013-01-30	72.039 mi
Registration #9	2013-06-22	74.464 mi
Registration #10	2014-06-20	77.327 mi
Registration #11	2015-06-08	79.971 mi
Registration #12	2016-06-20	83.038 mi
Registration #13	2016-06-20	83.038 mi
Registration #14	2016-06-20	83.038 mi
Registration #15	2016-06-20	83.038 mi
Registration #16	2016-06-20	83.038 mi
Registration #17	2016-06-20	83.038 mi
Registration #18	2016-06-20	83.038 mi
Registration #19	2016-06-20	83.038 mi
Registration #20	2016-06-20	83.038 mi
Registration #21	2016-06-20	83.038 mi
Registration #22	2016-06-20	83.038 mi
Registration #23	2016-06-20	83.038 mi
Registration #24	2016-06-20	83.038 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1437 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	AZJ 720635