



HONDA



HN600SA


report date: 2024-03-29

General information

Make	HONDA
Model	INSIGHT IMA ES
Colour	Silver
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	121 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-08-20
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #16 2023-08-24 11:02

MOT test number 769311887837

Result ✓ Passed

Next expiry date 2024-08-30

Advice Headlamp has a product on the lens but not seriously reducing light output deteriorated (4.1.4 (b))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-08-26 09:27

MOT test number 261263402138

Result ✓ Passed

Advice Front Headlamp has a product on the lens but not seriously reducing light output deteriorated (4.1.4 (b))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #14 2021-08-31 17:20

MOT test number 167869673351

Result ✓ Passed

**MOT #13** 2021-08-31 16:54**MOT test number** 280955638208**Result** ✗ Failed**Fail** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))**Fail** Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**MOT #12** 2020-10-06 11:29**MOT test number** 160697318641**Result** ✓ Passed**MOT #11** 2020-10-06 08:45**MOT test number** 514775248429**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-10-02 09:05**MOT test number** 687052642770**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-10-11 14:27**MOT test number** 204858906301**Result** ✓ Passed

**MOT #8** 2018-10-11 08:38**MOT test number** 129827710421**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2017-10-11 10:00**MOT test number** 612899178368**Result** ✓ Passed**MOT #6** 2017-10-04 09:22**MOT test number** 966810380610**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #5** 2016-10-06 11:01**MOT test number** 883291857230**Result** ✓ Passed**MOT #4** 2016-09-30 15:15**MOT test number** 622914894881**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)



MOT #3	2015-11-18 15:55
MOT test number	533361874620
Result	✓ Passed
MOT #2	2014-11-18 14:31
MOT test number	646212124352
Result	✓ Passed
MOT #1	2013-11-14 11:18
MOT test number	728188813321
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	HN600SA
Plate since	2024-03-29
Current registration	HN600SA
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-19
Last registration	2023-08-24
Complete history	See info



Registration #1	2010-11-19	25 mi
Registration #2	2013-11-14	9.275 mi
Registration #3	2014-11-18	10.336 mi
Registration #4	2015-11-18	11.624 mi
Registration #5	2016-09-30	12.950 mi
Registration #6	2016-10-06	13.001 mi
Registration #7	2017-10-04	25.084 mi
Registration #8	2017-10-11	25.094 mi
Registration #9	2018-10-11	37.437 mi
Registration #10	2019-10-11	38.377 mi
Registration #11	2019-10-11	38.377 mi
Registration #12	2019-10-11	38.377 mi
Registration #13	2019-10-11	38.377 mi
Registration #14	2019-10-11	38.377 mi
Registration #15	2019-10-11	38.377 mi
Registration #16	2019-10-11	38.377 mi
Registration #17	2019-10-11	38.377 mi
Registration #18	2019-10-11	38.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2000807