





General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Black
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F







Internet history

Entry	1
Date	

Pictures

2021-09-29

42

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	38
Total items failed	14

MOT #23		2024-01-12 17:16
MOT test	number	586055728455
Result		🗸 Passed
Next exp	iry date	2025-01-11
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Gearbox very noisey	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



KW55EZH report date: 2024-03-28

MOT #22	2024-01-08 14:28
MOT test number	451394701453
Result	🗙 Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Gearbox very noisey	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7	' (g) (i))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #21	. 2022-12-28 1	0:21
MOT test	t number 823953273	3613
Result	🗸 Pa	ssed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge tyre out of shape inside edge (5.2.3 (e))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice system re	Front Service brake imbalance requirements only just met. It would appear that the braking equires adjustment or repair. (1.2.1 (b) (i))	

МОТ #20	2021-12-17 11:59
MOT test number	205596383038
Result	✓ Passed



KW55EZH report date: 2024-03-28

MOT #19		2021-12-17 11:59
MOT test number		720685831666
Result		🗙 Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	

MOT #18	2021-01-04 1	L4:40
MOT test	number 26872594	1466
Result	🗸 Pa	assed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Lower Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #17		2021-01-04 14:40
MOT test number		417770121116
Result		🗙 Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Nearside Front T	yre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear L	ower Brake pipe corroded, covered in grease or other material (1	.1.11 (c))

MOT #16		2019-12-31 14:37
MOT test	number	428246753911
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	



KW55EZH report date: 2024-03-28

MOT #15		2019-12-31 14:37
MOT test number		454584975223
Result		🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #14	2019-12-31 12:44
MOT test number	444982992274
Result	🗙 Failed
 Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no lor of dirt (6.1.7 (g) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) 	nger prevents the ingress
MOT #13	2018-07-04 14:33
MOT test number	988415220937
Result	✓ Passed

MOT #12	2018-07-04 11:08
MOT test number	459079349257
Result	🗙 Failed
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #11	2017-07-10 11:30
MOT test number	885057612367
Result	✓ Passed



✓ Passed



MOT #10	2016-06-25 13:54
MOT test number	762541403905
Result	✓ Passed
МОТ #9	2015-06-10 11:16
MOT test number	836781165131
Result	✓ Passed
MOT #8	2014-06-17 10:27
MOT test number	728938464142

Result

MOT #7		2013-07-01 15:23
MOT test	number	226132383400
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	

МОТ #6	2013-07-01 10:30
MOT test number	237952283182
Result	× Failed
Notice Child seat fitted not allowing full inspection of adult belt	
Fail Front parking (secondary) brakes imbalanced (3.7.8.6b)	
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



KW55	EZH
report date:	2024-03-28

MOT #5		2012-07-03 15:58
MOT test	number	287495682427
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #4			2012-07-03 15:58
MOT test	number		598235282192
Result			🗙 Failed
Advice	Nearside Rear D	irection indicator slightly discoloured (1.4.A.2f)	
Notice Child seat fitted not allowing full inspection of adult belt			
Pass wit (7.4.B.3b)	h rectification	Exhaust emits an excessive level of metered smoke	for a turbo charged engine
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)			

MOT #3	2011-07-01 09:27
MOT test number	485422681149
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #2	2010-06-30 13:02
MOT test number	750931980101
Result	✓ Passed

MOT #1	2009-06-30 17:47
MOT test number	873771189182
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 11 January 2025
Tax status	Valid until 1 September
Days left	125
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate number plates.	
Number of plates	
Current registration	
Plate since	
Carrent registration	
Current registration	
Current registration Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-02-23
Last registration	2024-01-12
Complete history	See info



Registration #1	2006-02-23	29 mi
Registration #2	2009-06-30	22.909 mi
Registration #3	2010-06-30	29.617 mi
Registration #4	2011-07-01	36.475 mi
Registration #5	2012-07-03	43.860 mi
Registration #6	2013-07-01	50.586 mi
Registration #7	2013-07-01	50.586 mi
Registration #8	2014-06-17	57.597 mi
Registration #9	2015-06-10	62.606 mi
Registration #10	2016-06-25	66.769 mi
Registration #11	2017-07-10	71.807 mi
Registration #12	2018-07-04	76.685 mi
Registration #13		10.000 mi
Registration #14		11.777 est
-		11.777 est 11.777 est
Registration #14		11.777 est 11.777 est 11.777 est
Registration #14 Registration #15		0
Registration #14 Registration #15 Registration #16		0.777 es 0.777 es 0.777 es 0.777 es
Registration #14 Registration #15 Registration #16 Registration #17		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		0.577 es 0.577 es 0.577 es 0.577 es 0.577 es 0.577 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		0
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		0

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg
Additional information	
Additional information Fuel tank capacity	54 I
	54 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5