



SB6IFDZ

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Silver
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-06
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-15
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	33
Total items failed	7

MOT #14	2024-01-05 11:42
MOT test number	477412424218
Result	✓ Passed
Next expiry date	2025-01-15
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-01-16 15:31
MOT test number	350146785142
Result	✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #12**

2023-01-06 12:12

MOT test number

471965492706

Result**✗ Failed****Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2021-12-04 13:58

MOT test number

388842328581

Result**✓ Passed****MOT #10**

2020-10-30 12:24

MOT test number

580750657182

Result**✓ Passed****Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Emission test aborted no values recorded**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2020-10-30 12:24**MOT test number** 817822657370**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Emission test aborted no values recorded**MOT #8** 2019-11-21 16:37**MOT test number** 197166508591**Result** ✓ Passed**MOT #7** 2019-11-21 11:36**MOT test number** 446583887643**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2018-11-14 17:18**MOT test number** 540052725891**Result** ✓ Passed

**MOT #5** 2018-11-14 09:33**MOT test number** 198875857064**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #4** 2017-11-21 14:36**MOT test number** 680201718157**Result** ✓ Passed**MOT #3** 2016-11-10 08:56**MOT test number** 712906359471**Result** ✓ Passed**MOT #2** 2016-01-13 09:09**MOT test number** 975458259426**Result** ✓ Passed**Advice** Engine covers fitted**Advice** Nearside Rear tyre small nail in tread area**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened small marks around outer face (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread slightly deteriorated (6.3.1d)**Advice** Under trays fitted**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened small marks around outer face (3.5.1i)**MOT #1** 2015-01-07 09:03**MOT test number** 186997805021**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 January 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SB61FDZ
Plate since	2019-03-28
Current registration	 SB61FDZ
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-13
Last registration	2024-01-05
Complete history	See info



Registration #1	2012-01-13	23 mi
Registration #2	2015-01-07	31.782 mi
Registration #3	2016-01-13	46.729 mi
Registration #4	2016-11-10	57.029 mi
Registration #5	2017-11-21	69.719 mi
Registration #6	2018-11-14	78.907 mi
Registration #7	2018-11-14	78.907 mi
Registration #8	2019-11-21	86.294 mi
Registration #9	2019-11-21	86.294 mi
Registration #10	2019-11-21	86.294 mi
Registration #11	2019-11-21	86.294 mi
Registration #12	2019-11-21	86.294 mi
Registration #13	2019-11-21	86.294 mi
Registration #14	2019-11-21	86.294 mi
Registration #15	2019-11-21	86.294 mi
Registration #16	2019-11-21	86.294 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAYCK90899