



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 S
Colour	Blue
Year of manufacture	2006
Top speed	103 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 2



Date	2021-09-28
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-07
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-12-06
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	45
Total items failed	32

MOT #22 2023-12-07 12:38**MOT test number** 798076969089**Result** Passed**Next expiry date** 2024-12-06

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #21 2022-11-17 12:45**MOT test number** 323964168251**Result** Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2022-11-09 09:10**MOT test number** 446844957764**Result** ✗ Failed

- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #19 2021-10-05 15:32**MOT test number** 943767147125**Result** ✓ Passed**MOT #18** 2020-11-09 11:30**MOT test number** 672748421346**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2019-09-19 13:09

MOT test number

714696702776

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner dege (5.2.3 (e))

MOT #16

2019-09-06 12:15

MOT test number

342682179114

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner dege (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #15

2018-09-11 09:23

MOT test number

497157337646

Result

✓ Passed

**MOT #14**

2018-09-05 15:34

MOT test number

548060168563

Result**✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #13

2017-09-07 15:11

MOT test number

374452460027

Result**✓ Passed**

- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Advice** Exhaust has a minor leak of exhaust gases exhaust tailpipe (7.1.2)

MOT #12

2017-09-07 09:30

MOT test number

403259928398

Result**✗ Failed**

- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Exhaust has a minor leak of exhaust gases exhaust tailpipe (7.1.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #11

2016-09-08 13:49

MOT test number

299636334555

Result**✓ Passed**

**MOT #10** 2016-09-06 12:36**MOT test number** 288931564291**Result** ✗ Failed

- Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

MOT #9 2015-09-07 13:58**MOT test number** 543484187888**Result** ✓ Passed

- Advice** Torision bar bearings worn

MOT #8 2015-09-02 15:46**MOT test number** 432103416110**Result** ✗ Failed

- Fail** Centre Rear Statutory seat belt missing (5.1.1)

- Advice** Torision bar bearings worn

**MOT #7**

2014-09-06 08:51

MOT test number

265429844206

Result

✓ Passed

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Oil leak

MOT #6

2014-09-05 13:51

MOT test number

245908444271

Result

✗ Failed

Fail Offside Stop lamp not working (1.2.1b)

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Oil leak

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Nearside Headlamp aim too low (1.8)

MOT #5

2013-08-01 15:30

MOT test number

335793913281

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Play in steering rack inner joint(s)

Notice Child seat fitted not allowing full inspection of adult belt

Notice Engine covers fitted obscuring some components in the engine bay

Notice Standard fitment seat belt missing

**MOT #4**

2013-08-01 15:30

MOT test number

147003413223

Result

✗ Failed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Play in steering rack inner joint(s)
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Standard fitment seat belt missing

MOT #3

2012-07-14 10:53

MOT test number

987546892170

Result

✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)

MOT #2

2011-07-30 10:59

MOT test number

199861411246

Result

✓ Passed

- Notice** Centre rear seat belt missing
- Notice** Steering rack has slight play in both arms
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/f tyre low on edge



MOT #1	2010-07-21 12:14
MOT test number	591912800256
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-29
Last registration	2023-12-07
Complete history	See info



Registration #1	2006-09-29	23 mi
Registration #2	2010-07-21	47.218 mi
Registration #3	2011-07-30	72.329 mi
Registration #4	2012-07-14	85.505 mi
Registration #5	2013-08-01	96.479 mi
Registration #6	2014-09-05	103.957 mi
Registration #7	2014-09-06	103.957 mi
Registration #8	2015-09-02	107.851 mi
Registration #9	2015-09-07	107.853 mi
Registration #10	2016-09-06	113.818 mi
Registration #11	2016-09-08	113.818 mi
Registration #12	2017-09-07	118.617 mi
Registration #13	2018-09-07	123.417 mi
Registration #14	2019-09-07	128.217 mi
Registration #15	2020-09-07	133.017 mi
Registration #16	2021-09-07	137.817 mi
Registration #17	2022-09-07	142.617 mi
Registration #18	2023-09-07	147.417 mi
Registration #19	2024-03-29	152.217 mi
Registration #20	2024-03-29	157.017 mi
Registration #21	2024-03-29	161.817 mi
Registration #22	2024-03-29	166.617 mi
Registration #23	2024-03-29	171.417 mi
Registration #24	2024-03-29	176.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1472 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1186 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

FD881646956