





report date: 2024-03-28

General information

Make	LEXUS
Model	NX 300H F SPORT
Colour	Grey
Year of manufacture	2017
Top speed	112 mph
0 - 60 mph	9.2 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	155 BHP
Max. torque	210 Nm at 4.400 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	53.3 mpg
Consumption extra urban	55.4 mpg
Consumption combined	54.3 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-11
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #6		2024-04-08 09:09
MOT test	number	273614683835
Result		✓ Passed
Next expi	ry date	2025-04-11
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #5		2024-04-08 07:48
MOT test	number	903484112079
Result		× Failed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4		2023-04-06 07:47
MOT test	number	382170123322
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2022-04-08 13:44
MOT test	number	806468718152
Result		✓ Passed
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or con	rds (5.2.3 (d) (i))

MOT #2	2021-04-12 13:42
MOT test number	743888196051
Result	✓ Passed
MOT #1	2020-09-14 15:36
MOT test number	605217912058
Result	✓ Passed

CarCheck.co.uk page 4/11



NV67VMU report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	G
First licence fee (12 months)	£ 200,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-01
Last registration	2024-04-08
Complete history	See info



Registration #1	2017-09-01	15 mi
Registration #2	2020-09-14	26.004 mi
Registration #3		11.777 es
Registration #4	2021-04-12	26.059 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	82%
Pedestrian	69%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2130 mm
Height	1645 mm
Length	4640 mm
Wheel base	2660 mm
Kerb weight	1785 kg
Max. allowed weight	2395 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11