



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVTI NV
Colour	Blue
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	158 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	175 g/km
CO2 label	H





MOT history

MOT expiry date	2021-11-18
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	31
Total items failed	10

MOT #19	2020-11-19 12:52
MOT test number	139089373476
Result	✓ Passed
Next expiry date	2021-11-18
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Brake backing plate slightly corroded.
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Rear Brake backing plate slightly corroded.

**MOT #18** 2020-11-19 12:52**MOT test number** 307328697090**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Nearside Rear Brake backing plate slightly corroded.**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Offside Rear Brake backing plate slightly corroded.**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #17** 2019-11-19 12:02**MOT test number** 434119639813**Result** ✓ Passed

**MOT #16** 2019-11-13 17:25**MOT test number** 698426253320**Result** ✗ Failed

- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

MOT #15 2018-10-24 11:33**MOT test number** 734742176841**Result** ✓ Passed**MOT #14** 2017-10-31 11:41**MOT test number** 706185614415**Result** ✓ Passed**MOT #13** 2017-10-31 11:41**MOT test number** 986390318230**Result** ✗ Failed

- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #12 2016-10-31 16:23**MOT test number** 940288288551**Result** ✓ Passed**MOT #11** 2015-11-04 15:16**MOT test number** 438290237767**Result** ✓ Passed

**MOT #10** 2014-11-11 12:51**MOT test number** 437935614408**Result** ✓ Passed

- Notice** Steering rack bushes slightly worn
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Nsf/osf tyres perrished

MOT #9 2013-12-05 15:41**MOT test number** 497419233422**Result** ✓ Passed

- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Notice** Tyres starting to perrish

MOT #8 2012-12-08 12:41**MOT test number** 596763742302**Result** ✓ Passed**MOT #7** 2011-11-29 15:19**MOT test number** 457203431335**Result** ✓ Passed

- Notice** Centre to rear tailbox joints corroded!
- Notice** Rear brake pipe ferrules slightly corroded!

**MOT #6** 2010-12-07 15:16**MOT test number** 371181540303**Result** ✓ Passed**MOT #5** 2009-12-11 10:01**MOT test number** 331965449307**Result** ✓ Passed**MOT #4** 2008-12-11 10:15**MOT test number** 121406848318**Result** ✓ Passed**MOT #3** 2007-12-13 09:23**MOT test number** 631137947340**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2006-12-14 09:32**MOT test number** 702998746378**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2005-12-19 11:55**MOT test number** 100483055303**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
5 January 2021

✕
MOT

Expired:
18 November 2021

Tax status	Expired at 5 January 2021
Days left	1209 days too late
MOT expiry date	18 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-12-14
Last registration	2020-11-19
Complete history	See info



Registration #1	2002-12-14	18 mi
Registration #2	2005-12-19	34.888 mi
Registration #3	2006-12-14	41.068 mi
Registration #4	2007-12-13	46.872 mi
Registration #5	2008-12-11	52.330 mi
Registration #6	2009-12-11	56.273 mi
Registration #7	2010-12-07	60.174 mi
Registration #8	2011-11-29	63.246 mi
Registration #9	2012-12-08	68.801 mi
Registration #10	2013-12-05	72.869 mi
Registration #11	2014-12-02	76.937 mi
Registration #12	2015-12-01	81.005 mi
Registration #13	2016-11-30	85.073 mi
Registration #14	2017-11-29	89.141 mi
Registration #15	2018-11-28	93.209 mi
Registration #16	2019-11-27	97.277 mi
Registration #17	2020-11-19	101.345 mi
Registration #18	2020-11-19	101.345 mi
Registration #19	2020-11-19	101.345 mi
Registration #20	2020-11-19	101.345 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1700 mm
Length	3865 mm
Wheel base	2280 mm
Kerb weight	1235 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ1022556