





## General information

Make	HYUNDAI
Model	I30 ACTIVE
Colour	Blue
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history		
Entry 1		
Date	2021-06-16	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



## MOT history

MOT expiry date	2025-05-14
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #12		2024-04-24 09:00
MOT test number		275675315179
Result		✓ Passed
Next expiry date		2025-05-14
Advice Oil leak, but not o	excessive (8.4.1 (a) (i))	
Advice Exhaust has a mi	inor leak of exhaust gases cracked around ex	(haust catalyst (6.1.2 (a))
Advice Front Brake disc	worn, but not excessively nearside/offside (1	.1.14 (a) (i))
Advice Nearside Front Tr	rack rod end ball joint has slight play (2.1.3 (k	b) (i))

#### MOT #11 2024-04-23 10:20 **MOT test number** 799931163495 Result × Failed Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Front Brake disc worn, but not excessively nearside/offside (1.1.14 (a) (i)) **Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Fail Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Exhaust has a minor leak of exhaust gases cracked around exhaust catalyst (6.1.2 (a))





MOT #10	2023-05-15 17:24
MOT test	number 915764089902
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively nearside/offside (1.1.14 (a) (i))
Advice	Nearside Rear Nail in tyre
Advice	Front Brake disc worn, but not excessively nearside/offside (1.1.14 (a) (i))
Advice requires a	Front Brakes imbalanced requirements only just met. It would appear that the braking system djustment or repair. (1.2.1 (b) (i))
<b>Minor</b> (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

МОТ #9	2022-06-11 16:00
MOT test number	356238503869
Result	✓ Passed

MOT #8		2022-06-11 16:00
MOT test number		946594428553
Result		🗙 Failed
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #7	2021-06-21 16:42
MOT test number	671662658296
Result	✓ Passed

MOT #6		2021-06-21 16:42
MOT test number		248965784412
Result		🗙 Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	





MOT #5		2020-11-23 09:14
MOT test	number	590402638351
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2019-05-21 14:40
MOT test number	595549088164
Result	✓ Passed

MOT #3		2018-05-09 07:53
MOT test n	umber	925968848935
Result		✓ Passed
Advice	Rear tyres starting to perish and split	
Advice	Screw in nearside rear tyre	
Advice	Engine covers and under trays fitted	

MOT #2	2017-05-24 09:46
MOT test number	286125219235
Result	✓ Passed
MOT #1	2016-05-27 10:31
MOT test number	406205246022

MOT test number	406385246932
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
<b>Tax due:</b> 1 June 2024	Expires: 14 May 2025
Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 May 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	







#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-29
Last registration	2024-04-24
Complete history	<u>See info</u>



Registration #1	2013-05-29	16 mi
Registration #2	2016-05-27	25.631 mi
Registration #3	2017-05-24	31.903 mi
Registration #4	2018-05-09	37.536 mi
Registration #5	2019-05-21	43.995 mi
Registration #6	2020-11-23	53.914 mi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		10.300 est

More info >





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1306 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

### **Engine number**

## G4FADZ540430