





report date: 2024-03-28

### General information

Make	FORD
Model	ECOSPORT ST-LINE
Colour	Black
Year of manufacture	2019
Top speed	115 mph
0 - 100 km/h	12.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	92 kW / 125 HP / 138 BHP
Max. torque	170 Nm at 1.400 rpm
<b>Engine capacity</b>	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.9 mpg
Consumption extra urban	50.0 mpg
Consumption combined	43.5 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

### Entry 1

Date 2022-04-28

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2025-04-27
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #5		2024-04-06 13:57
MOT test	number	720573810913
Result		✓ Passed
Next expi	ry date	2025-04-27
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Tyre worn close to legal limit/worn on edge also cracking (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #4		2024-04-06 10:06
MOT test	number	796996105693
Result		<b>×</b> Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
<b>Fail</b> N	earside Front Tyre has a bulge, caused by separation or partial failure of its	structure (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Tyre worn close to legal limit/worn on edge also cracking (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



FA19PGY report date: 2024-03-28

MOT #3 2023-04-28 13:44

**MOT test number** 818989006634

MOT #2 2023-04-28 13:44

MOT test number 713658943918

Result × Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #1** 2022-04-28 13:25

**MOT test number** 896215458446

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	27 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

FA19PGY

report date: 2024-03-28

# For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here.

## Plate changes

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-08-12
Last registration	2024-04-06
Complete history	See info



Registration #1	2019-08-12	18 mi
Registration #2		77,777 66
Registration #3	2022-04-28	23.571 mi
Registration #4	2023-04-28	29.719 mi
Registration #5		11.777 es
Registration #6		77,777 66
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	77%
Pedestrian	58%
Safety systems	55%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1713 mm
Length	4096 mm
Wheel base	2519 mm
Kerb weight	1249 kg

# Additional information

Fuel tank capacity	52 I
Number of axles	2
Engine number	KC80937

CarCheck.co.uk page 11/11