



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D3 ES
Colour	White
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 2

Date	2023-10-10
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-08-31
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-31
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #12 2024-03-08 11:48

MOT test number 231794257185

Result ✓ Passed

Next expiry date 2025-03-31

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2023-04-01 11:18

MOT test number 237759345102

Result ✓ Passed

MOT #10 2023-03-31 13:48

MOT test number 755537838748

Result ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Windscreen washer not working (3.5 (a))

**MOT #9** 2022-08-03 10:50**MOT test number** 174437936655**Result** ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8 2021-07-12 14:50**MOT test number** 997132939107**Result** ✓ Passed**MOT #7** 2020-07-14 13:42**MOT test number** 405337747701**Result** ✓ Passed**MOT #6** 2019-07-05 13:50**MOT test number** 643872006857**Result** ✓ Passed**MOT #5** 2018-07-16 10:08**MOT test number** 359719446844**Result** ✓ Passed**MOT #4** 2017-07-19 15:44**MOT test number** 201698158815**Result** ✓ Passed

Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2016-08-04 11:10
MOT test number	150193699195
Result	✓ Passed

MOT #2	2015-09-25 15:30
MOT test number	731836766065
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit bald/worn on inner edge (4.1.E.1)

MOT #1	2014-09-05 15:13
MOT test number	456308444293
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 March 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2024-03-08
Complete history	See info



Registration #1	2011-09-30	15 mi
Registration #2	2014-09-05	39.017 mi
Registration #3	2015-09-25	54.704 mi
Registration #4	2016-08-04	69.773 mi
Registration #5	2017-07-19	79.812 mi
Registration #6	2018-07-16	93.997 mi
Registration #7	2019-07-05	108.267 mi
Registration #8	2020-07-14	119.663 mi
Registration #9	2021-06-29	131.277 mi
Registration #10	2022-06-29	143.277 mi
Registration #11	2023-06-29	155.277 mi
Registration #12	2024-03-08	167.277 mi
Registration #13	2024-03-08	179.277 mi
Registration #14	2024-03-08	191.277 mi
Registration #15	2024-03-08	203.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1732 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	915313