



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Silver
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-08
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-05
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	25
Total items failed	4

MOT #14 2023-06-06 10:03

MOT test number 655712076162

Result ✓ Passed

Next expiry date 2024-06-05

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin Approx. 2mm (1.1.13 (a) (ii))

MOT #13 2022-07-13 08:18

MOT test number 560960941525

Result ✓ Passed

- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #12 2021-08-07 10:45

MOT test number 730925054995

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #11	2020-06-12 13:28
MOT test number	719518622959
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-06-07 10:46
MOT test number	390550745723
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall 205-55-16 (5.2.3 (d) (i))

MOT #9	2018-05-22 15:08
MOT test number	376304137068
Result	✓ Passed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2018-05-22 08:50**MOT test number** 239587922715**Result** ✗ Failed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-06-06 08:17**MOT test number** 187187671389**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-06-13 10:42**MOT test number** 141891831321**Result** ✓ Passed**MOT #5** 2015-06-04 09:42**MOT test number** 176275255150**Result** ✓ Passed**MOT #4** 2014-05-15 15:40**MOT test number** 469635134195**Result** ✓ Passed

**MOT #3** 2014-05-15 09:51**MOT test number** 895355234187**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-14 12:59**MOT test number** 139335563145**Result** ✓ Passed**Notice** Offside front tyre perished**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres slightly perished**MOT #1** 2012-05-04 11:51**MOT test number** 207885222176**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-03
Last registration	2023-06-06
Complete history	See info



Registration #1	2009-06-03	9 mi
Registration #2	2012-05-04	3.479 mi
Registration #3	2013-06-14	16.300 mi
Registration #4	2014-05-15	29.751 mi
Registration #5	2014-05-15	29.751 mi
Registration #6	2015-06-04	44.373 mi
Registration #7	2016-06-13	57.371 mi
Registration #8	2017-06-06	68.855 mi
Registration #9	2018-06-06	75.377 mi
Registration #10	2019-06-06	81.889 mi
Registration #11	2020-06-06	88.401 mi
Registration #12	2021-06-06	94.913 mi
Registration #13	2022-06-06	101.425 mi
Registration #14	2023-06-06	107.937 mi
Registration #15	2024-06-06	114.449 mi
Registration #16	2025-06-06	120.961 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9G49373