



HV04NGF

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE CLASSIC
Colour	Red
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	325 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-05
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-03-24
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	52
Total items failed	7

MOT #24	2024-03-05 16:21
---------	------------------

MOT test number	660368801448
-----------------	--------------

Result	✗ Failed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
MAJOR	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Front Brake hose excessively stretched (1.1.12 (b) (ii))

**MOT #23**

2023-03-13 12:10

MOT test number

375741124806

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 2.7mm and worn on inner edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2.8mm and worn on inner edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin on 2mm (1.1.13 (a) (ii))

MOT #22

2023-03-10 09:17

MOT test number

915135010876

Result

✗ Failed

- MAJOR** Offside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2.8mm and worn on inner edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin on 2mm (1.1.13 (a) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 2.7mm and worn on inner edge (5.2.3 (e))

**MOT #21**

2022-03-25 12:52

MOT test number

864976411761

Result

✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #20**

2022-03-17 14:23

MOT test number

211550570422

Result

✗ Failed

Advice Offside Side repeater slightly discoloured (4.4.3 (a))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Upper Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))**DANGEROUS** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**MAJOR** Offside Headlamp aim too far to the right (4.1.2 (a))**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #19** 2021-03-23 11:28**MOT test number** 741573590874**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin innside (1.1.13 (a) (ii))**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both innside (1.1.14 (a) (ii))**MOT #18** 2020-03-19 10:47**MOT test number** 214605273725**Result** ✓ Passed**MOT #17** 2020-03-19 10:47**MOT test number** 254158614323**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #16** 2019-03-21 12:17**MOT test number** 663667631158**Result** ✓ Passed**MOT #15** 2018-03-20 12:04**MOT test number** 996072248421**Result** ✓ Passed**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**MOT #14** 2017-03-23 09:41**MOT test number** 929728652868**Result** ✓ Passed

**MOT #13** 2016-03-17 10:20**MOT test number** 919259708732**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2015-03-19 09:16**MOT test number** 198478975451**Result** ✓ Passed**MOT #11** 2014-03-12 12:36**MOT test number** 486271474007**Result** ✓ Passed**MOT #10** 2013-03-13 13:24**MOT test number** 329502773051**Result** ✓ Passed**MOT #9** 2013-03-13 10:33**MOT test number** 196622473044**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #8** 2012-03-20 11:53**MOT test number** 549360382015**Result** ✓ Passed

**MOT #7** 2012-03-20 09:49**MOT test number** 367840882077**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #6** 2011-03-23 13:21**MOT test number** 278132781034**Result** ✗ Failed**Pass with rectification** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #5** 2011-03-23 13:21**MOT test number** 238002081011**Result** ✓ Passed**MOT #4** 2010-03-11 11:47**MOT test number** 464520970005**Result** ✓ Passed**Notice** Plastic sill and under engine covers**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2009-03-10 10:05**MOT test number** 871989369057**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2008-03-03 12:26
MOT test number	191873968046
Result	✓ Passed

MOT #1	2007-03-07 10:05
MOT test number	193226867004
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-12
Last registration	2024-03-05
Complete history	See info



Registration #1	2004-03-12	22 mi
Registration #2	2007-03-07	35.516 mi
Registration #3	2008-03-03	48.482 mi
Registration #4	2009-03-10	61.380 mi
Registration #5	2010-03-11	74.974 mi
Registration #6	2011-03-23	84.569 mi
Registration #7	2012-03-20	90.736 mi
Registration #8	2012-03-20	90.736 mi
Registration #9	2013-03-13	92.770 mi
Registration #10	2013-03-13	92.770 mi
Registration #11	2014-03-12	95.031 mi
Registration #12	2015-03-19	96.728 mi
Registration #13	2016-03-17	98.334 mi
Registration #14	2016-03-17	98.334 mi
Registration #15	2016-03-17	98.334 mi
Registration #16	2016-03-17	98.334 mi
Registration #17	2016-03-17	98.334 mi
Registration #18	2016-03-17	98.334 mi
Registration #19	2016-03-17	98.334 mi
Registration #20	2016-03-17	98.334 mi
Registration #21	2016-03-17	98.334 mi
Registration #22	2016-03-17	98.334 mi
Registration #23	2016-03-17	98.334 mi
Registration #24	2016-03-17	98.334 mi
Registration #25	2016-03-17	98.334 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0405281915126B