





General information

Make	HONDA
Model	HR-V 4WD
Colour	Silver
Year of manufacture	2001
Top speed	94 mph
0 - 60 mph	12.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	101 BHP
Max. torque	135 Nm at 3.400 rpm
Engine capacity	1.590 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	37.2 mpg
Consumption combined	33.6 mpg
CO2 emission	201 g/km
CO2 label	К





MOT history

MOT expiry date	2021-02-21
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	34
Total items failed	2

MOT #13		2020-02-22 10:01
MOT test	number	433610524512
Result		✓ Passed
Next exp	iry date	2021-02-21
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))	
Advice	Engine bay covers and under body trays	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))		
Minor Nearside Obligatory mirror slightly damaged glass cracked (3.3 (b) (i))		
Advice	Noise from under car on pullaway	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))

MOT #12	2017-01-24 09:40
MOT test number	528947595109
Result	Passed
Advice Engine management light on	



LB51KHW
report date: 2024-03-28

MOT #11	2017-01-23 12:41
MOT test number	183407340116
Result	🗙 Failed
 Fail Nearside Stop lamp not working (1.2.1b) Advice Engine management light on Fail Offside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2) 	
MOT #10	2016-01-05 10:14
MOT test number	789265931705
Result	✓ Passed

Result		V Passeu
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #9	2014-12-0)3 09:28
MOT test	number 346947	7334348
Result		Passed
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
Notice	Eng oil low	
Notice	Offside rear tyre is spliting	
Advice	Offside Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Offside front tyre is spliting and badly cut	
Advice	Nearside Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	





MOT #8		2014-01-15 15:44
MOT test	number	899005914023
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.	1.2a)
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #7 2012-12-14 13:25 **MOT test number** 438289142391 Result Passed Notice Eng oil low Notice Sill covers fitted Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Shock absorber has a light misting of oil (2.7.3) Notice Child seat fitted not allowing full inspection of adult belt Notice Non obligatory mirror damaged Advice Front Brake pad(s) wearing thin (3.5.1g)

МОТ #6	2011-12-02 10:24
MOT test number	199246231355
Result	✓ Passed
Notice N/s mirror glass brokern	

MOT #5	2010-11-08 12:25
MOT test number	491542310326
Result	✓ Passed





MOT #4		2009-10-16 09:31
MOT test n	umber	923219389251
Result		✓ Passed
Notice	O/s front tyre worne inside tread	
MOT #2		
MOT #3		2008-10-16 13:52
MOT test n	umber	563500398269
Result		✓ Passed
MOT #2		2007-10-25 14:20
MOT test n	umber	144868997293
Result		✓ Passed
MOT #1		2006-10-24 11:41
MOT test n	umber	870297896211
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

X Untaxed Tax expired: 15 December 2020	X MOT Expired: 21 February 2021
Tax status	Expired at 15 December 2020
Days left	1230 days too late
MOT expiry date	21 February 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes See in this check if this HONDA had different number plat	A5
Number of plates	9
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2001-11-09
Last registration	2020-02-22
Complete history	See info



Registration #1	2001-11-09	20 mi
Registration #2	2006-10-24	10.850 mi
Registration #3	2007-10-25	16.376 mi
Registration #4	2008-10-16	23.646 mi
Registration #5	2009-10-16	32.844 mi
Registration #6	2010-11-08	39.779 mi
Registration #7	2011-12-02	45.885 mi
B 1 1 1 1 1		
Registration #8		11,717,468
Registration #8 Registration #9		11,117 es
-		01,000 est 01,000 est 01,000 est
Registration #9		01,000 es
Registration #9 Registration #10		01,000 es
Registration #9 Registration #10 Registration #11		01,007 46 01,007 46 01,007 46 01,007 46 01,007 46 01,007 46

More info >





Dimensions & weight

Width	2000 mm
Height	1700 mm
Length	4110 mm
Kerb weight	1125 kg
Additional information	
Free Lines in a second star	

Fuel tank capacity	55
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D16W11118031