



**DE58PHO**

report date: 2024-03-29

General information

Make	AUDI
Model	A6 TDI LIMITED EDITION
Colour	Grey
Year of manufacture	2009
Top speed	126 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed CVT

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	178 g/km
CO2 label	I





## MOT history

MOT expiry date	2021-09-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	31
Total items failed	4

## MOT #12 2020-09-14 13:14

MOT test number 354324886108

Result ✓ Passed

Next expiry date 2021-09-13

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

## MOT #11 2019-09-10 14:18

MOT test number 210457768268

Result ✓ Passed

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Alternator belt starting to crack and perish

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2018-09-01 13:15

**MOT test number**

261815007383

**Result**

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9**

2018-09-01 13:15

**MOT test number**

108274721774

**Result**

✗ Failed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Pass with rectification** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Pass with rectification** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #8** 2017-08-31 14:38**MOT test number** 671759015261**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-08-08 14:00**MOT test number** 197216402257**Result** ✓ Passed**MOT #6** 2016-08-08 14:00**MOT test number** 646486434168**Result** ✗ Failed**Pass with rectification** Offside Steering rack gaiter insecure (2.2.D.2d)**MOT #5** 2015-08-03 11:57**MOT test number** 607965215230**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear shock covers insecure**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2014-07-18 12:59**MOT test number** 738339394175**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-06-28 16:43
MOT test number	835859373186
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2012-06-27 14:26
MOT test number	138459072135
Result	✓ Passed

MOT #1	2012-06-27 14:26
MOT test number	236799972110
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-01-12
Last registration	2020-09-14
Complete history	<a href="#">See info</a>



Registration #1	2009-01-12	19 mi
Registration #2	2012-06-27	75.277 mi
Registration #3	2013-06-28	98.477 mi
Registration #4	2014-07-18	119.060 mi
Registration #5	2015-08-03	119.105 mi
Registration #6	2016-08-08	126.253 mi
Registration #7	2017-08-08	126.253 mi
Registration #8	2017-08-08	126.253 mi
Registration #9	2017-08-08	126.253 mi
Registration #10	2017-08-08	126.253 mi
Registration #11	2017-08-08	126.253 mi
Registration #12	2017-08-08	126.253 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1459 mm
Length	4916 mm
Wheel base	2843 mm
Kerb weight	1565 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	BRE 185330