



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC AWD T SE
Colour	Grey
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	8.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	210 BHP
Max. torque	320 Nm at 4.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	27.2 mpg
CO2 emission	244 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-06-09
Pictures	55
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	29
Total items failed	12

MOT #22	2024-01-09 15:00
MOT test number	493063326239
Result	✓ Passed
Next expiry date	2025-01-24
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #21	2024-01-08 11:50
MOT test number	983031715069
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #20	2023-01-19 11:02
MOT test number	920764464444
Result	✓ Passed

MOT #19	2022-01-13 11:38
MOT test number	568420737156
Result	✓ Passed

**MOT #18**

2021-01-11 10:36

MOT test number

302452472317

Result

✓ Passed

Advice Parking brake has little reserve travel**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 26% (1.2.1 (b) (i))**MOT #17**

2019-07-03 09:05

MOT test number

534999819656

Result

✓ Passed

Advice Offside Rear door has slight body damage**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16**

2019-07-03 09:05

MOT test number

539952577835

Result

✗ Failed

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear door has slight body damage**MOT #15**

2018-07-25 14:15

MOT test number

675602194868

Result

✓ Passed

Minor Offside Side repeater insecure (4.4.1 (c) (i))

**MOT #14** 2017-07-19 14:56**MOT test number** 799012111995**Result** ✓ Passed**MOT #13** 2016-07-20 15:34**MOT test number** 827056610847**Result** ✓ Passed**MOT #12** 2016-07-20 08:22**MOT test number** 642278720891**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-07-15 14:04**MOT test number** 905026995186**Result** ✓ Passed**MOT #10** 2014-06-23 16:08**MOT test number** 717254874139**Result** ✓ Passed**Notice** Sill covers fitted

**MOT #9**

2014-06-23 10:03

MOT test number

246644474469

Result**✗ Failed**

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)
- Notice** Sill covers fitted
- Fail** Offside Registration plate lamp not working (1.1.C.1d)

MOT #8

2013-06-27 16:22

MOT test number

417258573156

Result**✓ Passed**

- Notice** Sill covers fitted
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Fuel cap seal perishing
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2013-06-26 10:20**MOT test number** 576467373178**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Sill covers fitted
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Rear wheel bearing rough when rotated (2.6.1)
- Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Fuel cap seal perishing

MOT #6 2012-07-04 15:53**MOT test number** 517426482106**Result** ✓ Passed

- Notice** Sill covers fitted
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2011-06-30 08:55**MOT test number** 725051381196**Result** ✓ Passed**MOT #4** 2011-06-28 14:14**MOT test number** 897359371163**Result** ✗ Failed

- Fail** Nearside Front Ball joint has excessive play (2.2.B.1f)



MOT #3	2010-06-30 13:27
MOT test number	200211480402
Result	✓ Passed
MOT #2	2009-07-22 13:18
MOT test number	611373309221
Result	✓ Passed
MOT #1	2008-07-22 10:31
MOT test number	250924508241
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
24 January 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RY05YGF
Plate since	2024-03-29
Current registration	RY05YGF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-07-22
Last registration	2024-01-09
Complete history	See info



Registration #1	2005-07-22	20 mi
Registration #2	2008-07-22	30.405 mi
Registration #3	2009-07-22	40.480 mi
Registration #4	2010-06-30	46.411 mi
Registration #5	2011-06-28	57.684 mi
Registration #6	2011-06-30	57.758 mi
Registration #7	2012-07-04	70.185 mi
Registration #8	2013-06-26	82.986 mi
Registration #9	2013-06-27	82.986 mi
Registration #10	2014-06-23	95.545 mi
Registration #11	2014-06-23	95.545 mi
Registration #12	2015-07-15	108.311 mi
Registration #13	2015-07-15	108.311 mi
Registration #14	2015-07-15	108.311 mi
Registration #15	2015-07-15	108.311 mi
Registration #16	2015-07-15	108.311 mi
Registration #17	2015-07-15	108.311 mi
Registration #18	2015-07-15	108.311 mi
Registration #19	2015-07-15	108.311 mi
Registration #20	2015-07-15	108.311 mi
Registration #21	2015-07-15	108.311 mi
Registration #22	2015-07-15	108.311 mi
Registration #23	2015-07-15	108.311 mi
Registration #24	2015-07-15	108.311 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1630 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	3624052