






report date: 2024-03-29

## General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	98 BHP
Max. torque	310 Nm at 1.300 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	39.2 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29


## Internet history

### Entry 1

Date 2021-07-26

Pictures 15

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-25
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	25
Total items failed	0

MOT #10		2023-09-26 13:02
MOT test	number	605990750814
Result		<b>✓</b> Passed
Next expi	ry date	2024-09-25
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in ex	cessive movement (5.3.4
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4 (a)

MOT #9		2022-08-10 12:52
MOT test	number	512697254922
Result		✓ Passed
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	)
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021-08-06 15:32
MOT test number	172668684154
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MAJOR** 

SP12YWC

report date: 2024-03-29

**MOT #7** 2021-08-04 16:25 873086009760 **MOT** test number Result × Failed **MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c)) **MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c)) **MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a)) **MAJOR** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) **MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Nearside Suspension arm pin or bush excessively worn rear bush of front arm (5.3.4 (a) (i))

MOT test number

406615815374

Result

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Service brake fluctuating, but not excessively both (1.2.1 (e))

Advice Brake pipe corroded, covered in grease or other material front to rear x2 (1.1.11 (c))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #5	2019-01-28 15:27
MOT test number	649009928281
Result	<b>✓</b> Passed
MOT #4	2018-02-22 17:21
MOT test number	121391877247
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

**MOT #3** 2017-02-28 11:04 549595549252 **MOT** test number Result ✓ Passed **Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Rear number plate loose **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2

MOT test number

Result

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

 MOT #1
 2015-02-25 13:16

 MOT test number
 836046155051

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29





Days left 93

MOT expiry date 25 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SP12YWC report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

o mile mesery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



SP12YWC report date: 2024-03-29

## Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-03-30
Last registration	2023-09-26
Complete history	See info



Registration #1	2012-03-30	9 mi
Registration #2	2015-02-25	23.447 mi
Registration #3	2016-02-24	30.897 mi
Registration #4	2017-02-28	38.015 mi
Registration #5	2018-02-22	42.292 mi
Registration #6	2019-01-28	45.564 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



SP12YWC report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BM22990

CarCheck.co.uk page 12/12