



report date: 2024-03-29

General information

Make	KIA
Model	RIO 2
Colour	Grey
Year of manufacture	2017
Top speed	103 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-10-13
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-30
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #5	2023-09-18 09:04
MOT test number	679989413857
Result	✓ Passed
Next expiry date	2024-09-30
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4	2022-09-19 10:38
MOT test number	126389108345
Result	✓ Passed

MOT #3	2021-09-20 15:19
MOT test number	660662610289
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing also tread starting to get low (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #2** 2021-09-20 08:36**MOT test number** 492006599105**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing also tread starting to get low (5.2.3 (d) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #1** 2020-10-01 09:30**MOT test number** 710526310887**Result** ✓ Passed**Advice** Both front tyres worn to 3mm or just below**Advice** Rear wiper split



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	NL67LWZ
Plate since	2019-09-29
Current registration	NL67LWZ
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-29
Last registration	2023-09-18
Complete history	See info



Registration #1	2017-09-29	10 mi
Registration #2	2020-10-01	18.176 mi
Registration #3	2021-09-20	26.299 mi
Registration #4	2021-09-20	26.299 mi
Registration #5	2023-09-18	26.299 mi
Registration #6	2023-09-18	26.299 mi
Registration #7	2023-09-18	26.299 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4050 mm
Wheel base	4065 mm
Kerb weight	1198 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LAGP128869