



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Grey
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-25
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #23	2023-07-11 09:11
MOT test number	743848250511
Result	✓ Passed
Next expiry date	2024-07-10
Minor	Nearside Windscreen damaged but not adversely affecting driver's view substantial damage to nearside & central area (3.2 (a) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Nearside Play in steering rack inner joint(s)

MOT #22	2023-07-04 13:36
MOT test number	667968815897
Result	✗ Failed
Fail	Offside Headlamp aim projected beam image is obviously incorrect kick up beam goes both directions (4.1.2 (c))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view substantial damage to nearside & central area (3.2 (a) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Fail	Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Play in steering rack inner joint(s)

MOT #21	2022-06-27 11:46
MOT test number	937355683812
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both discs pitted (1.1.14 (a) (ii))
Advice	Front Brake disc worn, but not excessively both discs lipped (1.1.14 (a) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #20** 2021-06-30 11:18**MOT test number** 123735701126**Result** ✓ Passed**MOT #19** 2020-12-11 17:18**MOT test number** 982544182984**Result** ✓ Passed

- Advice** Under trays fitted some components not seen
- Minor** Electrical wiring slightly deteriorated engine bay (4.11 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Advice** Offside Rear Body damage
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Spare tyre defective
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear body damage
- Advice** Offside Rear Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18**

2020-12-11 13:03

MOT test number

535074355313

Result**✗ Failed**

- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Under trays fitted some components not seen
- Advice** Offside Rear Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))
- Advice** Offside Rear Body damage
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Electrical wiring slightly deteriorated engine bay (4.11 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Spare tyre defective
- Advice** Nearside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))
- Advice** Nearside Rear body damage
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #17

2020-12-09 17:37

MOT test number

178544229217

Result**✗ Failed**

- Fail** Rear Inner Brake pad(s) less than 1.5 mm thick both, (1.1.13 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #16** 2019-12-14 15:51**MOT test number** 506103887332**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both sides, (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides, (1.1.14 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #15** 2018-12-17 15:42**MOT test number** 937959541901**Result** ✓ Passed**MOT #14** 2017-11-28 15:37**MOT test number** 536981982386**Result** ✓ Passed**MOT #13** 2017-11-28 11:36**MOT test number** 991196953048**Result** ✗ Failed**Advice** Rear Tyre worn close to the legal limit both x2 (4.1.E.1)**Fail** Offside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (4.1.D.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (4.1.D.1a)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Stop lamp not working (1.2.1b)

**MOT #12** 2016-12-28 11:24**MOT test number** 107590166810**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside front tyre worn on edges**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-12-28 11:24**MOT test number** 222023352333**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside front tyre worn on edges**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-12-30 11:14**MOT test number** 590145471518**Result** ✓ Passed**MOT #9** 2015-12-29 16:16**MOT test number** 958173625334**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Stop lamp not working (1.2.1b)

**MOT #8** 2014-11-29 11:49**MOT test number** 597113434317**Result** ✓ Passed**MOT #7** 2014-11-29 11:49**MOT test number** 568123134337**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #6** 2013-12-28 14:36**MOT test number** 166622563340**Result** ✓ Passed**MOT #5** 2013-12-28 12:44**MOT test number** 217582163317**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2012-12-31 13:49**MOT test number** 706806962385**Result** ✓ Passed**MOT #3** 2011-12-10 13:55**MOT test number** 868394541329**Result** ✓ Passed**MOT #2** 2010-07-14 14:33**MOT test number** 250175890173**Result** ✓ Passed



MOT #1	2009-11-25 14:37
MOT test number	813349129365
Result	✓ Passed



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-11-30
Last registration	2023-07-11
Complete history	See info



Registration #1	2006-11-30	25 mi
Registration #2	2009-11-25	6.399 mi
Registration #3	2010-07-14	7.003 mi
Registration #4	2011-12-10	17.752 mi
Registration #5	2012-12-31	20.561 mi
Registration #6	2013-12-28	23.812 mi
Registration #7	2013-12-28	23.813 mi
Registration #8	2014-11-29	26.432 mi
Registration #9	2015-12-29	29.606 mi
Registration #10	2015-12-30	29.650 mi
Registration #11	2016-12-28	33.381 mi
Registration #12	2016-12-28	33.381 mi
Registration #13	2016-12-28	33.381 mi
Registration #14	2016-12-28	33.381 mi
Registration #15	2016-12-28	33.381 mi
Registration #16	2016-12-28	33.381 mi
Registration #17	2016-12-28	33.381 mi
Registration #18	2016-12-28	33.381 mi
Registration #19	2016-12-28	33.381 mi
Registration #20	2016-12-28	33.381 mi
Registration #21	2016-12-28	33.381 mi
Registration #22	2016-12-28	33.381 mi
Registration #23	2016-12-28	33.381 mi
Registration #24	2016-12-28	33.381 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1205 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D011354