





General information

Make	MINI
Model	ROADSTER COOPER S
Colour	Blue
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 2

Date Pictures 2021-08-14

12

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-08-12

43

View report



source: autotrader.co.uk









MOT history

MOT expiry date	2024-08-16
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #11	2023-08-09 14:54
MOT test number	334488136071
Result	✓ Passed
Next expiry date	2024-08-16
Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	
Advice Temporary fuel cap fitted	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	

MOT #10		2022-08-12 11:36
MOT test	number	530264688396
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

МОТ #9	2021-08-17 14:35
MOT test number	161416116993
Result	✓ Passed





МОТ #8	2021-03-15 16:54
MOT test number	132653851651
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing also 9 yrs old (5.2.3 (d) (ii))	

MOT #7	2020-03-17 16:34
MOT test number	587020049269
Result	✓ Passed

МОТ #6	2019-09-30 14:44
MOT test number	878273896365
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i))	ing in excessive movement
Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice N/s/r and n/s/f tyres cut in outer sidewalls	

MOT #5		2018-09-15 09:59
MOT test	number	424090660902
Result		✓ Passed
Advice	N/s/r tyre sidewall cut	
Advice	Front tyres starting to wear unevenly on inner edges	
Advice	Slight distortion to o/s/f wheel rim	

MOT #4	2017-10-09 16:31
MOT test number	362553218317
Result	✓ Passed





MOT #3	2017-04-05 10:58
MOT test number	182030142751
Result	✓ Passed
Advice Bulb not working warning light on	
MOT #2	2017-02-07 14:33
MOT test number	261600878871
Result	✓ Passed
MOT #1	2017-02-04 10:03
MOT test number	173539681212
Result	🗙 Failed
Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 16 August 2024
Tax status	Valid until 1 September
Days left	126
MOT expiry date	16 August 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class48BandESingle payment (12 months)£ 180,00,-Single six month payment£ 99,00,-Total payable by 12 monthly instalments£ 189,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	L'ESN'
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-28
Last registration	2023-08-09
Complete history	See info



Registration #1	2013-05-28	13 mi
Registration #2	2017-02-04	16.179 mi
Registration #3	2017-02-07	16.181 mi
Registration #4	2017-04-05	16.199 mi
Registration #5	2017-10-09	19.243 mi
Registration #6	2018-09-15	22.948 mi
Registration #7	2019-09-30	26.690 mi
Registration #8		11.777 est
Registration #8 Registration #9		11.777 es
-		11.227 es 11.227 es 11.227 es
Registration #9		11.227 es 11.227 es 11.227 es 11.227 es
Registration #9 Registration #10		11,227 46 11,227 46 11,227 46 11,227 46 11,227 46
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/12

Engine number

A079J479