



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 SE LUX
Colour	Blue
Year of manufacture	2012
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	29
Total items failed	2

MOT #11	2024-04-16 15:53
MOT test number	741166699429
Result	✓ Passed
Next expiry date	2025-04-15
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #10	2024-04-16 12:40
MOT test number	412337321332
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Windscreen washer not working (3.5 (a))

MOT #9	2022-08-03 10:31
MOT test number	428219976811
Result	✓ Passed

**MOT #8**

2022-07-25 16:03

MOT test number

194131207725

Result**✗ Failed**

- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Offside Headlamp insecure (4.1.1 (c))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7

2020-11-19 14:01

MOT test number

786836445025

Result**✓ Passed**

- Advice** Under tray fitted obscuring view
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Engine cover fitted obscuring view

MOT #6

2019-05-24 10:07

MOT test number

406405029064

Result**✓ Passed**

- Advice** Under tray fitted obscuring view
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Engine cover fitted obscuring view
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Suspension component pin or bush slightly worn both rear stabiliser link bushes (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #5** 2018-05-24 14:33**MOT test number** 100770238879**Result** ✓ Passed**Advice** Engine cover fitted obscuring view**Advice** Under tray fitted obscuring view**MOT #4** 2017-05-26 11:51**MOT test number** 704445123875**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2017-05-26 11:25**MOT test number** 937840644986**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2016-05-25 15:19**MOT test number** 147659415882**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2015-05-27 14:37
MOT test number	127327945185
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 August 2023

✓

MOT

Expires:
15 April 2025

Tax status	Expired at 1 August 2023
Days left	273 days too late
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-29
Last registration	2024-04-16
Complete history	See info



Registration #1	2012-06-29	25 mi
Registration #2	2015-05-27	34.329 mi
Registration #3	2016-05-25	45.358 mi
Registration #4	2017-05-26	55.214 mi
Registration #5	2017-05-26	55.214 mi
Registration #6	2018-05-24	66.170 mi
Registration #7	2019-05-24	76.565 mi
Registration #8	2020-05-22	86.577 mi
Registration #9	2021-05-20	96.589 mi
Registration #10	2022-05-18	106.601 mi
Registration #11	2023-05-16	116.613 mi
Registration #12	2024-04-16	126.625 mi
Registration #13	2024-04-16	126.625 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1373 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2128799