





report date: 2024-03-29

General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2017
Top speed	148 mph
0 - 60 mph	6.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	350 Nm at 4.500 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2022-02-02


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2022-01-06	
------	------------	--


Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-11-19

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

$M \cap T$	hictory
	history

MOT expiry date

MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	2
MOT #8	2024-04-03 13:5
MOT test number	69012944601
Result	✓ Passe
Next expiry date	2025-04-0
MOT #7	2023-03-31 17:2
MOT test number	55547334814
Result	✓ Passe

2025-04-02

MOT #6	2022-08-31 07:01
MOT test number	765270117561
Result	✓ Passed

MOT #5	2022-02-23 15:29
MOT test number	530421904288
Result	✓ Passed

MOT #4	2022-01-15 08:40
MOT test number	841608878189
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #2

MOT test number

681382699239

Result

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1 2020-11-09 12:40 978914160098 **MOT** test number Result × Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front tyre worn on outer edge **Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Advice Front Brake disc worn, but not excessively Lipped and corroded on inner face (1.1.14 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

	_
Date	

Damage 1

Category

Type

Damage 2

Date

Category

Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
O	,

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-09-29
Last registration	2024-04-03
Complete history	See info



Registration #1	2017-09-29	11 mi
Registration #2	2020-11-09	17.438 mi
Registration #3	2021-01-02	18.029 mi
Registration #4	2021-01-04	18.029 mi
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1565 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11