





report date: 2024-03-30

#### General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Red
Year of manufacture	2005
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.800 rpm
Engine capacity	1.124 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-30

### Internet history

#### Entry 1

Date 2021-12-10

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-30

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-18
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	15
Total items failed	3

MOT #21	2023-12-19 12:40
MOT test number	132449833258
Result	<b>✓</b> Passed
Next expiry date	2024-12-18
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #20	2022-12-16 10:07
MOT test number	972939454600
Result	<b>✓</b> Passed
Advice Oil sump corroded	

MOT #19	2021-12-14 17:28
MOT test number	706319081971
Result	✓ Passed

MOT #18		2021-12-14 14:55
MOT test	number	134952861753
Result		<b>X</b> Failed
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
MAJOR	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-30

**MOT #17** 2021-05-27 13:48

**MOT test number** 307998817200

MOT #16 2021-05-27 13:48

**MOT test number** 422036797066

Result X Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #15** 2020-06-22 09:38

**MOT test number** 851021838831

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-05-30 12:53

MOT test number 469814877417

Result \rightarrow Passed

**MOT #13** 2019-05-30 10:22

MOT test number 296327765188

Result × Failed

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure

(5.2.3 (d) (ii))

**MOT #12** 2018-05-18 10:36

**MOT test number** 792393109533

**Result** 
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-30

MOT #11 2017-05-26 09:03 **MOT test number** 576705947808 Result ✓ Passed MOT #10 2017-05-26 09:03 **MOT test number** 116824862222 Result × Failed Pass with rectification Nearside Side repeater incorrect colour (1.4.A.2f) Pass with rectification Offside Side repeater incorrect colour (1.4.A.2f)

MOT test number

Result

Advice Offside Side repeater slightly discoloured (1.4.A.2f)

Advice Offside Inner rack end has slight play felt at the wheel

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear wiper split

MOT #8	2015-05-28 15:52
MOT test number	589228045171
Result	✓ Passed
MOT #7	2014-05-29 17:15
MOT test number	565089944136
Result	✓ Passed
Notice Items removed from driver's view prior to test	

CarCheck.co.uk page 5/13



report date: 2024-03-30

MOT #6		2013-06-12 13:26
<b>MOT</b> test	number	298473863451
Result		✓ Passed
Advice	Offside Front Side repeater slightly discoloured (1.4.A.2f)	
Advice	Nearside Front Side repeater slightly discoloured (1.4.A.2f)	

MOT #5	2012-06-12 13:05
MOT test number	737594562190
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2011-06-13 11:38
MOT test number	187544461190
Result	<b>✓</b> Passed

MOT #3	2010-06-18 12:58
MOT test number	244789860132
Result	✓ Passed

MOT #2	2009-06-11 11:32
MOT test number	451802569169
Result	<b>√</b> Passed

MOT #1	2008-06-16 12:32
MOT test number	251878368112
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-30

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	18 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-30

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-30

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-30

Owner	hictory
OWITEI	HIISLULY

C Miles Miscory	
For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	
PROPERTY.	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	K UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-30

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-30

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-05
Last registration	2023-12-19
Complete history	See info



Registration #1	2005-03-05	11 mi
Registration #2	2008-06-16	14.337 mi
Registration #3	2009-06-11	19.172 mi
Registration #4	2010-06-18	23.517 mi
Registration #5	2011-06-13	29.088 mi
Registration #6	2012-06-12	34.825 mi
Registration #7	2013-06-12	39.450 mi
Registration #8	2014-05-29	43.924 mi
Registration #9	2015-05-28	47.128 mi
Registration #10	2016-05-21	49.728 mi
Registration #11	2017-05-26	51.988 mi
Registration #12	2017-05-26	51.988 mi
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-30

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

**Engine number** 

FP7N4789506