





### General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	Silver
Year of manufacture	2014
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В





## MOT history

MOT expiry date	2025-03-22
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	16
Total items failed	21

MOT #14	2024-03-20 14:37
MOT test number	127533078631
Result	✓ Passed
Next expiry date	2025-03-22
Advice Front Tyre worn close to legal limit/worn on edge both worn on edges (5.2.3 (e))	

МОТ #13	2024-03-15 15:40
MOT test number	230536614132
Result	🗙 Failed
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Fail         Nearside Front Service brake lagging in operation 39% (1.2.1 (d))	
<b>Fail</b> Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Front Tyre worn close to legal limit/worn on edge both worn on edges (5.2.3 (e)	)
Advice Nearside Play in steering rack inner joint(s) severe wear	
<b>Fail</b> Offside Headlamp aim unable to be tested (4.1.2 (b))	





MOT #12	2023-03-23 14:38
MOT test number	850776617618
Result	✓ Passed
Advice Nearside Front Play in steering rack inner joint(s)	
MOT #11	2023-03-21 11:07
MOT test number	392132402264
Result	🗙 Failed
<b>Fail</b> Nearside Headlamp insecure (4.1.1 (c))	
Advice Nearside Front Play in steering rack inner joint(s)	
Fail         Nearside Headlamp aim too low (4.1.2 (a))	

MOT #10	2022-04-29 16:01
MOT test number	251297477516
Result	✓ Passed

# Result

МОТ #9	2022-04-29 08:22
MOT test number	643401360591
Result	🗙 Failed
Advice Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))	
<b>Fail</b> Brake lever has insufficient reserve travel parkbrake (1.1.2 (a))	
<b>Fail</b> Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
<b>Fail</b> Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	
Fail         Nearside Rear Service brake excessively binding (1.2.1 (f))	





MOT #8	2021-08-24 11:38
MOT test number	192555712423
Result	✓ Passed
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely de	teriorated (6.1.7 (g) (i))
MOT #7	2021-08-23 15:02
MOT test number	469886942853
Result	🗙 Failed
<b>Fail</b> Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail Front Exhaust system insecure (6.1.2 (a))	
Fail         Nearside Front Headlamp aim projected beam image is obviously incorrect	t (4.1.2 (c))
Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))	

**Fail** Offside Front Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Front Undertray insecure (8.1.1 (b) (i))

МОТ #6	2020-08-26 13:55
MOT test number	562119062192
Result	✓ Passed

MOT #5		2020-08-26 13:55
MOT test number		430255245970
Result		🗙 Failed
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	





MOT #4		2019-08-28 09:37
MOT test	number	702988331357
Result		✓ Passed
Advice	Offside Rear Road wheel slightly distorted Inner rim (5.2.2 (c) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))	

MOT #3	2018-08-28 09:12
MOT test number	791267593050
Result	✓ Passed

MOT #2	2018-08-28 09:12
MOT test number	595058418249
Result	× Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Pass with rectification	Front Brake disc significantly and obviously worn BOTH (1.1.14 (a) (i))

MOT #1	2017-08-22 11:41
MOT test number	434972178450
Result	✓ Passed
Advice Front registration plate delaminated but not likely to be misread (6.3.1d)	



Tax & MOT check

X Untaxed Tax expired: 1 April 2024	<b>Expires:</b> 22 March 2025	✓ МОТ
Tax status		Expired at 1 April 2024
Days left		27 days too late
MOT expiry date		22 March 2025
Full MOT history		See MOT history
Tax calculation		
Vehicle class	49	
Band	В	

Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Rumber of plates	,
Rumber of plates Carrent registration	
Rumber of plates Carrent registration Fals since	
Rumber of protes Current registration Current registration	
Rumber of plates Carrent registration Fate since Fate since Fate since	1000-20-20





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-04-07
Last registration	2024-03-20
Complete history	See info



Registration #1	2014-04-07	25 mi
Registration #2	2017-08-22	23.644 mi
Registration #3	2018-08-28	28.348 mi
Registration #4	2018-08-28	28.348 mi
Registration #5	2019-08-28	34.951 mi
Registration #6	2020-08-26	42.343 mi
Registration #7	2020-08-26	42.343 mi
Registration #8	2021-08-23	62.582 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi

More info  $\rightarrow$ 





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CFWA427596