



report date: 2024-03-29

## General information

|                     |                          |
|---------------------|--------------------------|
| Make                | VAUXHALL                 |
| Model               | ANTARA EXCLUSIV CDTI S/S |
| Colour              | Grey                     |
| Year of manufacture | 2012                     |
| Top speed           | 117 mph                  |
| Gearbox             | 6 speed Manual           |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 161 BHP             |
| Max. torque             | 350 Nm at 2.000 rpm |
| Engine capacity         | 2.231 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 32.8 mpg            |
| Consumption extra urban | 50.4 mpg            |
| Consumption combined    | 42.8 mpg            |
| CO2 emission            | 170 g/km            |
| CO2 label               | H                   |





Internet history

Entry 3

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-08-18                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-11                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: cargurus.co.uk

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-10                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-09-27 |
| MOT pass rate      | 69 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 4          |
| Total advice items | 20         |
| Total items failed | 10         |

**MOT #13** 2023-09-05 13:45**MOT test number** 846063315189**Result** ✓ Passed**Next expiry date** 2024-09-27**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2022-09-28 12:51**MOT test number** 553842112180**Result** ✓ Passed**MOT #11** 2022-08-22 12:14**MOT test number** 912177115895**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Oxidisation to suspension components(springs , Sub frames etc)**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2021-07-28 11:39**MOT test number** 465743851933**Result** ✓ Passed**Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))**MOT #9** 2020-12-03 12:00**MOT test number** 173253318326**Result** ✓ Passed**MOT #8** 2019-08-07 13:50**MOT test number** 320960787183**Result** ✓ Passed**Advice** Offside Rear Outer tyre wall**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Tyre worn close to legal limit/worn on edge plus starting too perish (5.2.3 (e))**MOT #7** 2019-08-03 12:46**MOT test number** 310878959709**Result** ✗ Failed**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Tyre worn close to legal limit/worn on edge plus starting too perish (5.2.3 (e))**Advice** Offside Rear Outer tyre wall**Fail** Nearside Front Position lamp not working side (4.2.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #6** 2018-08-06 14:45**MOT test number** 387253803625**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-08-04 10:20**MOT test number** 415794034744**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both sides (4.1.E.1)**MOT #4** 2017-08-04 10:20**MOT test number** 406427704316**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working both sides (1.1.A.3b)**Advice** Front Tyre worn close to the legal limit both sides (4.1.E.1)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2016-07-27 10:35**MOT test number** 821005312985**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)



|                         |   |
|-------------------------|---|
| MOT #2                  | 2016-07-27 10:35  |
| MOT test number         | 252725807930  |
| Result                  | ✗ Failed  |
| Pass with rectification | Stop lamp not working both (1.2.1b)   |
| Advice                  | Front Tyre worn close to the legal limit both (4.1.E.1)                     |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2015-07-31 16:50 |
| MOT test number | 668432715211     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 January 2025

✓  
**MOT**  
  
Expires:  
27 September 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 January           |
| Days left        | 246                             |
| MOT expiry date  | 27 September 2024               |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | H          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|                |            |
|----------------|------------|
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |
| XXXXXX         | XXXXXXXXXX |
| XXXXXXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX     | XXXXXXXXXX |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2020-01-01  |
| Current registration |  <b>XXXXXX</b> |
| Plate since          | 2020-01-01  |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2012-12-13               |
| Last registration          | 2023-09-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2012-12-13 | 11 mi      |
| Registration #2  | 2015-07-31 | 19.834 mi  |
| Registration #3  | 2016-07-27 | 34.927 mi  |
| Registration #4  | 2016-07-27 | 34.927 mi  |
| Registration #5  | 2017-08-04 | 57.766 mi  |
| Registration #6  | 2017-08-04 | 57.766 mi  |
| Registration #7  | 2018-08-06 | 78.655 mi  |
| Registration #8  | 2019-08-03 | 100.158 mi |
| Registration #9  | 2019-08-07 | 100.365 mi |
| Registration #10 | 2019-08-07 | 100.365 mi |
| Registration #11 | 2019-08-07 | 100.365 mi |
| Registration #12 | 2019-08-07 | 100.365 mi |
| Registration #13 | 2019-08-07 | 100.365 mi |
| Registration #14 | 2019-08-07 | 100.365 mi |
| Registration #15 | 2019-08-07 | 100.365 mi |
| Registration #16 | 2019-08-07 | 100.365 mi |
| Registration #17 | 2019-08-07 | 100.365 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 95%                             |
| Children       | 84%                             |
| Pedestrian     | 46%                             |
| Safety systems | 71%                             |
| Overall rating | 81%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2085 mm |
| Height              | 1717 mm |
| Length              | 4596 mm |
| Wheel base          | 2707 mm |
| Kerb weight         | 1836 kg |
| Max. allowed weight | 2505 kg |

Additional information

|                 |                  |
|-----------------|------------------|
| Fuel delivery   | Direct Injection |
| Number of doors | 5                |
| Number of seats | 5                |
| Number of axles | 2                |
| Engine number   | 172361K          |