





report date: 2024-03-28

# General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Grey
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-28


# Internet history

# Entry 2

Date 2022-04-26

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-01-16	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-10-01
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	15
Total items failed	9

MOT #19	2023-10-02 16:19
MOT test number	549548340804
Result	✓ Passed
Next expiry date	2024-10-01

MOT #18	2023-01-13 10:11
MOT test number	513007548735
Result	<b>✓</b> Passed
Advice Corrosion to all under-floor components	

MOT #17	2022-01-21 14:49
MOT test number	994972226521
Result	✓ Passed

CarCheck.co.uk page 3/14



Fail

MT07YVX

report date: 2024-03-28

MOT test number
673781780311

Result

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2021-07-06 11:40
MOT test number	984963145744
Result	<b>✓</b> Passed

Nearside Rear Service brake excessively binding (1.2.1 (f))

MO1 #14	2021-01-26 15:45
MOT test number	202677572260
Result	✓ Passed

MOI #T2	2021-01-27 09.55
MOT test number	228014609110
Result	<b>×</b> Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #12** 2020-02-10 11:25 330452457708 **MOT** test number ✓ Passed Result **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #11

MOT test number

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10 2018-02-15 09:46

MOT test number 843127058189

Result ✓ Passed

MOT #9

MOT test number

454865058948

Result

✓ Passed

MOT #8 2015-09-01 10:09

MOT test number 875717562204

**Result** X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 235 40x18 (4.1.D.1a)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/14



MOT #7 2014-09-10 16:29

**MOT test number** 875773854259

**Result** ✓ Passed

**Notice** Age cracks nearside rear tyre also worn close to legal limit in parts of tread pattern

MOT #6 2014-09-09 15:07

**MOT test number** 415142154210

**Result** X Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Notice** Age cracks nearside rear tyre also worn close to legal limit in parts of tread pattern

**MOT #5** 2013-09-10 09:14

**MOT test number** 117283853222

Result \rightarrow Passed

**Notice** Age cracks in both rear tyres

**Notice** Nail in offside rear tyre

MOT #4 2012-09-17 13:23

**MOT test number** 757991962209

Result \( \sqrt{Passed} \)

Notice COVERS COVERING BRAKE PIPES

MOT #3 2012-09-15 12:24

**MOT test number** 306919752273

**Result** X Failed

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Notice COVERS COVERING BRAKE PIPES

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #2	2011-09-15 15:43
MOT test number	816218151249
Result	<b>✓</b> Passed
MOT #1	2010-08-16 15:23
MOT test number	272368520241

CarCheck.co.uk page 7/14



# Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	1 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Category

Date

Type



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner	biotom
UWNEI	nision
	1113601

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-08-22
Last registration	2023-10-02
Complete history	See info



Registration #2       2010-08-16       14.551 mi         Registration #3       2011-09-15       19.074 mi         Registration #4       2012-09-15       28.008 mi         Registration #5       2012-09-17       28.015 mi         Registration #6       2013-09-10       35.554 mi         Registration #7       2014-09-09       43.863 mi         Registration #8       2014-09-10       43.868 mi         Registration #9       2015-09-01       52.598 mi         Registration #10       2015-09-03       52.598 mi			
Registration #3 Registration #4 Registration #5 Registration #6 Registration #7 Registration #7 Registration #8 Registration #8 Registration #8 Registration #9 Registration #10 Registration #10 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #18 Registration #19 Registration #18 Registration #18 Registration #18 Registration #18 Registration #18 Registration #18 Registration #19 Registration #19 Registration #19 Registration #20 Registration #20 Registration #21	Registration #1	2007-08-22	12 mi
Registration #4 2012-09-15 28.008 mi Registration #5 2012-09-17 28.015 mi Registration #6 2013-09-10 35.554 mi Registration #7 2014-09-09 43.863 mi Registration #8 2014-09-10 43.868 mi Registration #9 2015-09-01 52.598 mi Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #18 Registration #19 Registration #19 Registration #20 Registration #20 Registration #21	Registration #2	2010-08-16	14.551 mi
Registration #5 Registration #6 2013-09-10 35.554 mi Registration #7 2014-09-09 43.863 mi Registration #8 2014-09-10 43.868 mi Registration #9 2015-09-01 52.598 mi Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21	Registration #3	2011-09-15	19.074 mi
Registration #6 2013-09-10 35.554 mi Registration #7 2014-09-09 43.863 mi Registration #8 2014-09-10 43.868 mi Registration #9 2015-09-01 52.598 mi Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #18 Registration #19 Registration #20 Registration #21	Registration #4	2012-09-15	28.008 mi
Registration #7  Registration #8  2014-09-09  43.863 mi Registration #8  2014-09-10  43.868 mi Registration #9  2015-09-01  52.598 mi Registration #10  2015-09-03  52.598 mi Registration #11  2018-02-15  77.582 mi Registration #13  Registration #14  Registration #15  Registration #16  Registration #17  Registration #18  Registration #19  Registration #20  Registration #21	Registration #5	2012-09-17	28.015 mi
Registration #8 2014-09-10 43.868 mi Registration #9 2015-09-01 52.598 mi Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #12 2018-02-15 2018-02-15 57.582 mi Registration #13 2018-02-15 2018	Registration #6	2013-09-10	35.554 mi
Registration #9 2015-09-01 52.598 mi Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #7	2014-09-09	43.863 mi
Registration #10 2015-09-03 52.598 mi Registration #11 2018-02-15 57.582 mi Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #8	2014-09-10	43.868 mi
Registration #11 2018-02-15 57.582 mi Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #9	2015-09-01	52.598 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #10	2015-09-03	52.598 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #11	2018-02-15	57.582 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #12		11.777 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #13		11.777 es
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #14		11.777 es
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21	Registration #15		11.777 es
Registration #18 Registration #19 Registration #20 Registration #21	Registration #16		11.777 es
Registration #19 Registration #20 Registration #21	Registration #17		11.777 es
Registration #20 Registration #21	Registration #18		11.777 es
Registration #21	Registration #19		11.777 es
	Registration #20		11.777 es
Registration #22	Registration #21		11.777 es
	Registration #22		0.00 44

More info >

CarCheck.co.uk page 13/14



# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2010 kg

# Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
CarChack caluk	220 14/14

CarCheck.co.uk page 14/14

Number of seats	4
Engine number	BMM 122233