





report date: 2024-03-29

General information

Make	BMW
Model	640 640I SE
Colour	Grey
Year of manufacture	2011
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	315 BHP
Max. torque	450 Nm at 1.300 rpm
Engine capacity	2.979 сс
Cylinders	6
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



P3RNL

report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-29

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-28

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-10
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #12	2023-08-09 10:51
MOT test number	421121367892
Result	✓ Passed
Next expiry date	2024-08-10
** offside mirror glass damaged **	
Advice Both rear tyres worn inner edges	

MOT #11	2022-08-11 10:57
MOT test number	679577908152
Result	✓ Passed
Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on the edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on the edge	e (5.2.3 (e))

MOT #10	2021-06-18 08:12
MOT test number	297347485601
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2019-09-23 13:06

MOT test number 548107363047

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Coolant leak

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #8 2018-09-25 15:01

MOT test number 981912762931

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm + worn on both edges (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2018-09-24 12:53

MOT test number 984744228260

Result ★ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm + worn on both edges (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2017-09-27 11:53

MOT test number 702552529719

Advice Both windscreen wipers slightly smeary

CarCheck.co.uk page 4/12



Result

Result

P3RNL report date: 2024-03-29

X Failed

Passed

MOT #5 2016-09-30 10:11

MOT test number 595135207126

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #4 2016-09-30 10:11

MOT test number 162174663080

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Pass with rectification Headlamp cleaning device inoperative (1.7.2)

Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #3 2015-08-25 11:42

MOT test number 439977635223

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #2 2014-08-27 15:25

MOT test number 638829734277

Result ✓ Passed

MOT #1 2014-03-12 10:35

MOT test number 177011674417

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ve?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-01
Last registration	2023-08-09
Complete history	See info



Registration #1	2011-03-01	10 mi
Registration #2	2014-03-12	33.799 mi
Registration #3	2014-08-27	36.653 mi
Registration #4	2015-08-25	45.008 mi
Registration #5	2016-09-30	51.006 mi
Registration #6	2016-09-30	51.006 mi
Registration #7	2017-09-27	56.984 mi
Registration #8	2018-09-24	59.997 mi
Registration #9		11.777 es
Registration #10		77,777 46
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		73,777 66
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1894 mm
Height	1365 mm
Length	4894 mm
Wheel base	2855 mm
Kerb weight	1840 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4	page 12/12

Number of axles 2

Engine number 14607735