



HG160SK

report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MAZDA          |
| Model               | cx-3 SE-L NAV  |
| Colour              | Red            |
| Year of manufacture | 2016           |
| Top speed           | 119 mph        |
| 0 - 60 mph          | 9.0 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 118 BHP             |
| Max. torque             | 204 Nm at 2.800 rpm |
| Engine capacity         | 1.998 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 38.2 mpg            |
| Consumption extra urban | 57.7 mpg            |
| Consumption combined    | 47.9 mpg            |
| CO2 emission            | 137 g/km            |
| CO2 label               | E                   |






Internet history

Entry 2



|               |                             |
|---------------|-----------------------------|
| Date          | 2023-09-09                  |
| Pictures      | 33                          |
| Listing price | <a href="#">View report</a> |



source: [cargurus.co.uk](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-15                  |
| Pictures      | 44                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2025-05-04 |
| <b>MOT pass rate</b>      | 60 %       |
| <b>MOT passed</b>         | 6          |
| <b>Failed MOT tests</b>   | 4          |
| <b>Total advice items</b> | 8          |
| <b>Total items failed</b> | 6          |

|                         |   |
|-------------------------|---|
| <b>MOT #10</b>          | 2024-04-23 14:47                                  |
| <b>MOT test number</b>  | 983766924822                                      |
| <b>Result</b>           | ✓ Passed  |
| <b>Next expiry date</b> | 2025-05-04  |
| <b>Advice</b>           | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

|                        |  |
|------------------------|--|
| <b>MOT #9</b>          | 2024-04-23 07:49   |
| <b>MOT test number</b> | 689540566856   |
| <b>Result</b>          | ✗ Failed   |
| <b>Advice</b>          | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| <b>Fail</b>            | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| <b>Advice</b>          | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                      |

|                        |                  |
|------------------------|------------------|
| <b>MOT #8</b>          | 2023-05-04 08:53 |
| <b>MOT test number</b> | 154213612418     |
| <b>Result</b>          | ✓ Passed         |

**MOT #7** 2023-05-04 08:53**MOT test number** 114634762031**Result** ✗ Failed

**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6** 2022-05-03 08:02**MOT test number** 536549430476**Result** ✓ Passed

**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Front Wipers slight smear.

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #5** 2021-05-05 09:05**MOT test number** 950479755025**Result** ✓ Passed**MOT #4** 2020-06-16 15:06**MOT test number** 588806523272**Result** ✓ Passed**MOT #3** 2020-06-16 09:55**MOT test number** 817195761719**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



|                 |                  |
|-----------------|------------------|
| MOT #2          | 2019-06-26 10:45 |
| MOT test number | 140150654695     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2019-06-26 10:11 |
| MOT test number | 181671950545     |
| Result          | ✗ Failed         |

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 May 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 October           |
| <b>Days left</b>        | 156                             |
| <b>MOT expiry date</b>  | 4 May 2025                      |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |



Damage history


Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2020-01-01    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2020-01-01    |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2016-06-30               |
| Last registration          | 2024-04-23               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2016-06-30 | 21 mi     |
| Registration #2  | 2019-06-26 | 29.364 mi |
| Registration #3  | 2019-06-26 | 29.364 mi |
| Registration #4  | 2020-06-16 | 38.343 mi |
| Registration #5  | 2020-06-16 | 38.343 mi |
| Registration #6  | 2021-05-05 | 42.856 mi |
| Registration #7  | 2022-05-20 | 55.277 mi |
| Registration #8  | 2023-05-20 | 55.277 mi |
| Registration #9  | 2023-05-20 | 55.277 mi |
| Registration #10 | 2023-05-20 | 55.277 mi |
| Registration #11 | 2023-05-20 | 55.277 mi |
| Registration #12 | 2023-05-20 | 55.277 mi |
| Registration #13 | 2024-04-23 | 55.277 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★☆                           |
| Adult          | 85%                             |
| Children       | 79%                             |
| Pedestrian     | 84%                             |
| Safety systems | 64%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1765 mm |
| Height              | 1535 mm |
| Length              | 4275 mm |
| Wheel base          | 2570 mm |
| Kerb weight         | 1155 kg |
| Max. allowed weight | 1690 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 48 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | PE 30840792      |