





General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Black
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



Internet history	
Entry 1	
Date	2021-02-03
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT #18		2019-11-14 12:53
MOT test	number	611070122721
Result		✓ Passed
Next expiry date 2020-1		2020-11-30
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Both rack ends slight play	

MOT #17		2019-11-14 12:53
MOT test number		424473156219
Result		🗙 Failed
Advice Both rack end	s slight play	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #16	2018-11-12 16:26
MOT test number	619184070910
Result	✓ Passed
Advice Nearside Front steering rack end slight play	

MOT #15	2018-11-12 13:21
MOT test number	313188347149
Result	🗙 Failed
 Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Fail All direction indicators incorrect colour all 4 (4.4.3 (a)) Advice Nearside Front steering rack end slight play 	

MOT #14	2017-11-09 14:27
MOT test number	490886595332
Result	✓ Passed
CarCheck.co.uk	page 3/12





MOT #13	2016-12-01 11:20
MOT test number	844863166664
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #12	2016-02-17 12:38
MOT test number	532051013947
Result	✓ Passed
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #11	2016-02-17 10:58
MOT test number	137816022411
Result	🗙 Failed
Fail Offside Headlamp not working on dipped beam (1.7.5a) Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #10	2015-02-14 10:03
MOT test number	447825945075
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #9		2015-02-14 10:03
MOT test number		599005445030
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)		
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #8	2014-02-19 17:22
MOT test number	938460654094
Result	✓ Passed

MOT #7		2013-04-20 10:29
MOT test	number	235280513434
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #6	2012-04-28 12:31
MOT test number	968919212100
Result	✓ Passed
MOT #5	2012-04-28 12:31

MOT test number		358839912129
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	





MOT #4		2011-04-19 11:03
MOT test	number	515479801134
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #3		2010-04-27 13:33
MOT test	number	363887210158
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Service light on	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #2	2010-04-27 11:07
MOT test number	904787310137
Result	🗙 Failed
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Service light on	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2009-04-25 10:33
MOT test number	232755619192
Result	✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-05-15
Last registration	2019-11-14
Complete history	See info



Registration #1	2006-05-15	13 mi
Registration #2	2009-04-25	24.920 mi
Registration #3	2010-04-27	34.264 mi
Registration #4	2010-04-27	34.264 mi
Registration #5	2011-04-19	41.461 mi
Registration #6	2012-04-28	50.165 mi
Registration #7	2013-04-20	56.493 mi
Registration #8	2014-02-19	59.507 mi
Registration #9	2015-02-14	69.037 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	D089414