



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D3 SE LUX
Colour	Black
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-09
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #12 2023-06-19 11:51

MOT test number 583367714888

Result ✓ Passed

Next expiry date 2024-06-22

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement radius arm (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement radius arm (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #11 2022-06-23 10:05

MOT test number 136443866889

Result ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement radius arm (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement radius arm (5.3.4 (a) (i))

MOT #10 2021-06-16 07:27

MOT test number 817861850307

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2021-06-15 15:41

MOT test number

347745559481

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8**

2020-06-17 14:52

MOT test number

820864509309

Result**✓ Passed****MOT #7**

2019-03-06 17:42

MOT test number

542783040221

Result**✓ Passed****Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6**

2018-03-06 09:53

MOT test number

577416113311

Result**✓ Passed****Advice** Rear tyres perished**Advice** Front tyres 2mm inner edge

**MOT #5** 2018-03-06 09:53**MOT test number** 595130380141**Result** ✗ Failed**Advice** Rear tyres perished**Advice** Front tyres 2mm inner edge**Pass with rectification** Bonnet retaining device ineffective (8.4.2)**MOT #4** 2017-03-10 14:10**MOT test number** 419743789330**Result** ✓ Passed**Advice** Rear tyres perished**MOT #3** 2016-03-10 09:30**MOT test number** 124570863282**Result** ✓ Passed**MOT #2** 2015-03-16 09:44**MOT test number** 439255875028**Result** ✓ Passed**MOT #1** 2014-03-26 08:56**MOT test number** 297675384005**Result** ✓ Passed**Notice** Front tyres perished



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 RK11WDY
Plate since	2024-03-29
Current registration	 RK11WDY
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-26
Last registration	2023-06-19
Complete history	See info



Registration #1	2011-03-26	13 mi
Registration #2	2014-03-26	27.370 mi
Registration #3	2015-03-16	35.776 mi
Registration #4	2016-03-10	45.913 mi
Registration #5	2017-03-10	53.504 mi
Registration #6	2018-03-06	59.547 mi
Registration #7	2018-03-06	59.547 mi
Registration #8	2019-03-20	59.547 mi
Registration #9	2019-03-20	59.547 mi
Registration #10	2019-03-20	59.547 mi
Registration #11	2019-03-20	59.547 mi
Registration #12	2019-03-20	59.547 mi
Registration #13	2019-03-20	59.547 mi
Registration #14	2019-03-20	59.547 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------