



NXI40EO


report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SE-L
Colour	Red
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 2

Date2023-12-12

Pictures8




source: g3remarketing.co.uk

Entry 1

Date2021-06-15

Pictures8

Listing priceView report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	3
Total items failed	6

MOT #9 2023-01-20 15:38

MOT test number 941240500302

Result ✗ Failed

- Fail** Offside Front Suspension arm pin or bush excessively worn FRONT BOTTOM ARM REAR BUSH (5.3.4 (a) (i))
- Fail** Emissions not tested EXCESS SMOKE (8.2.2.2 (e))
- Fail** Direction indicator incorrect colour BOTH REAR (4.4.3 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement FRONT BOTTOM ARM REAR BUSH (5.3.4 (a) (i))

MOT #8 2022-02-04 10:11

MOT test number 249969061561

Result ✓ Passed

MOT #7 2022-02-04 10:11

MOT test number 555066446135

Result ✗ Failed

- Pass with rectification** Front Headlamp aim too high (4.1.2 (a))

MOT #6 2021-02-15 15:55

MOT test number 495646701745

Result ✓ Passed

**MOT #5** 2020-02-04 14:56**MOT test number** 541382741946**Result** ✓ Passed**Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear spring cups (5.3.6 (a) (i))**Advice** Nail in nearside rear tyre**MOT #4** 2019-01-31 14:24**MOT test number** 364228340930**Result** ✓ Passed**MOT #3** 2018-02-02 12:50**MOT test number** 331924729235**Result** ✓ Passed**MOT #2** 2017-02-15 12:51**MOT test number** 328852579146**Result** ✓ Passed**MOT #1** 2017-02-14 10:29**MOT test number** 181794975063**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)



Tax & MOT check

X

Untaxed

Tax expired:
6 October 2023

X

MOT

Expired:
28 February 2023

Tax status	Expired at 6 October 2023
Days left	207 days too late
MOT expiry date	28 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-01
Last registration	2023-01-20
Complete history	See info



Registration #1	2014-03-01	18 mi
Registration #2	2017-02-14	65.523 mi
Registration #3	2017-02-15	65.524 mi
Registration #4	2018-02-02	78.680 mi
Registration #5	2019-01-31	85.803 mi
Registration #6	2020-02-04	94.889 mi
Registration #7	2020-05-20	95.277 mi
Registration #8	2020-05-20	95.277 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2750 mm
Kerb weight	1420 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	SH 30396232