



NAI2HNP

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Silver
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #11 2023-07-26 13:16

MOT test number 643154856978

Result ✓ Passed

Next expiry date 2024-07-29

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald on its inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Very low on its inner edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin On minimum thickness for MOT! (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10 2023-07-26 11:59

MOT test number 448319301418

Result ✗ Failed

- Advice** Front Brake pad(s) wearing thin On minimum thickness for MOT! (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald on its inner edge (5.2.3 (e))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Very low on its inner edge (5.2.3 (e))



MOT #9	2022-07-27 14:24
---------------	------------------

MOT test number	369961898526
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Brake pad(s) wearing thin Roughly 25% remaining - discs also have lipped edges (1.1.13 (a) (ii))
---------------	--

MOT #8	2021-07-30 12:10
---------------	------------------

MOT test number	917345750193
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2020-09-14 09:10
---------------	------------------

MOT test number	780095078668
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2019-09-20 10:15
---------------	------------------

MOT test number	379446268991
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2018-12-04 11:56
---------------	------------------

MOT test number	353007467702
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2018-01-22 15:09
---------------	------------------

MOT test number	783829148121
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-02-11 16:13
---------------	------------------

MOT test number	561485274790
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Under tray fitted obscuring some underside components
---------------	---



MOT #2	2016-02-12 13:07
MOT test number	379329605406
Result	✓ Passed

MOT #1	2015-02-13 12:10
MOT test number	365964945038
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-18
Last registration	2023-07-26
Complete history	See info



Registration #1	2012-04-18	21 mi
Registration #2	2015-02-13	19.948 mi
Registration #3	2016-02-12	24.817 mi
Registration #4	2017-02-11	28.125 mi
Registration #5	2018-01-22	34.013 mi
Registration #6	2018-12-04	40.799 mi
Registration #7	2019-09-20	44.981 mi
Registration #8	2019-09-20	44.981 mi
Registration #9	2019-09-20	44.981 mi
Registration #10	2019-09-20	44.981 mi
Registration #11	2019-09-20	44.981 mi
Registration #12	2019-09-20	44.981 mi
Registration #13	2019-09-20	44.981 mi
Registration #14	2019-09-20	44.981 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAYCK90899