





General information

| Make | BMW |
|---------------------|----------------------|
| Model | X4 XDRIVE20D M SPORT |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 132 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |





Internet history

Date Pictures 2021-07-13

18

Listing price

View report



source: cargurus.co.uk

| Entry 1 | | |
|----------|------------|--|
| Date | 2021-07-12 | |
| Pictures | 9 | |

Listing price

9 <u>View report</u>



source: autotrader.co.uk







MOT history

| MOT expiry date | 2025-05-14 |
|--------------------|------------|
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 10 |
| Total items failed | 4 |

| MOT #10 | 2024-04-18 14:06 | |
|---|------------------|--|
| MOT test number | 897731996290 | |
| Result | 🗸 Passed | |
| Next expiry date | 2025-05-14 | |
| MinorOffside Windscreen damaged but not adversely affecting driver's view upper part of screen has a stone chip (3.2 (a) (i))Advice (5.2.3 (e))Nearside Rear Tyre worn close to legal limit/worn on edge Wearing low on inner edge of tread | | |

| МОТ #9 | 2024-04-17 09:44 | |
|---|------------------|--|
| MOT test number | 374822851608 | |
| Result | 🗙 Failed | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing low on inner edge of tread (5.2.3 (e)) | | |
| Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | | |
| Minor Offside Windscreen damaged but not adversely affecting driver's view upper part of screen has a stone chip (3.2 (a) (i)) | | |
| | | |

| MOT #8 | 2023-05-15 10:22 | 8 |
|--|--|---|
| MOT test | number 995961417782 | 2 |
| Result | ✓ Passed | ł |
| Advice Offside Front Tyre worn close to legal limit/worn on edge worn low on outer egdes of treads (5.2.3 (e)) | | |
| Advice (5.2.3 (e)) | Nearside Front Tyre worn close to legal limit/worn on edge worn low on outer egdes of treads | |





| MOT #7 | 2023-05-10 08:51 |
|---|--------------------------------|
| MOT test number | 582245787608 |
| Result | 🗙 Failed |
| Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge worn low o (e)) | n outer egdes of treads (5.2.3 |
| Fail Headlamp cleaning device for LED or HID headlamp inoperative Both la | mps (4.1.6 (a) (ii)) |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn low on outer egdes of treads (5.2.3 (e)) | |
| MOT #6 | 2022-03-14 15:13 |
| MOT test number | 225945406074 |
| Result | ✓ Passed |
| MOT #5 | 2021-09-07 09:02 |
| MOT test number 444868896850 | |
| Result | ✓ Passed |
| MOT #4 | 2020-09-04 08:15 |
| MOT test number | 273718650290 |
| Result | ✓ Passed |
| MOT #3 | 2019-09-05 10:20 |
| MOT test number | 778315162765 |
| Result | ✓ Passed |
| MOT #2 | 2019-09-04 10:46 |
| MOT test number | 760892364504 |
| Result | 🗙 Failed |
| Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

CarCheck.co.uk





| MOT #1 | | 2018-09-04 09:34 |
|----------|---|------------------|
| MOT test | number | 362060765814 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |



Tax & MOT check

| Tax due: 1 March 2025 | ✓ Taxed | ↓ MOT Expires: 14 May 2025 | |
|---------------------------------|------------|---|--------|
| Tax status | | Valid until 1 M | arch |
| Days left | | | 307 |
| MOT expiry date | | 14 May | 2025 |
| Full MOT history | | <u>See MOT h</u> | istory |
| Tax calculation | | | |

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FERRE |
| Category | L'ERNPE |
| Туре | |
| Domogo 2 | AMPLE |
| Damage 2 | 6 - 0 - 0 |
| Date | |
| Category | AMP |
| Туре | |

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| *********** | |
|---|-------------|
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | , |
| | |
| Current registration | |
| Current registration Plate since | |
| Current registration Pate since Current registration | |
| Carrent registration Plate since Carrent registration Plate since | 8775-25-27 |





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 13 |
| First mileage registration | 2015-09-07 |
| Last registration | 2024-04-18 |
| Complete history | <u>See info</u> |



| Registration #1 | 2015-09-07 | 8 mi |
|------------------|------------|------------|
| Registration #2 | 2018-09-04 | 30.217 mi |
| Registration #3 | 2019-09-04 | 39.202 mi |
| Registration #4 | 2019-09-05 | 39.202 mi |
| Registration #5 | 2020-09-04 | 43.562 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 0566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 83% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1881 mm |
| Height | 1624 mm |
| Length | 4671 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1745 kg |
| Max. allowed weight | 2335 kg |
| Additional information | |
| Fuel tank capacity | 67 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|----------|
| Engine number | 51579342 |