



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD CTDI EX
Colour	Silver
Year of manufacture	2006
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	140 Nm at 4.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-16
Pictures	36
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	50
Total items failed	30

MOT #22	2023-11-03 14:28
MOT test number	433594855653
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Sills corroded and sill covers fitted
Advice	Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Power steering ram has slight seepage from a joint (2.1.5 (a))
Advice	Front and rear suspension components corroded
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive both sides (5.3.6 (a) (i))

**MOT #21**

2022-09-26 13:21

MOT test number

657238493243

Result

✓ Passed

Advice

Slight oil leak

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice

Sill guards fitted

Advice

Offside steering rack damp with oil

Advice

Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bushes nearside and offside (5.3.4 (a) (i))

MOT #20

2021-09-27 13:52

MOT test number

486735813926

Result

✓ Passed

Advice

Offside Front Power steering component has slight seepage from a component (2.1.5 (a))

MOT #19

2021-09-27 09:03

MOT test number

835117394443

Result

✗ Failed

Fail

Nearside Front Steering locking device missing TRACK ROD END (2.1.3 (d))

Fail

Offside Front Lower Steering locking device missing BALL JOINT (2.1.3 (d))

Advice

Offside Front Power steering component has slight seepage from a component (2.1.5 (a))

Fail

Offside Front Steering locking device missing (2.1.3 (d))

Fail

Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

**MOT #18** 2020-10-07 10:20**MOT test number** 967955641437**Result** ✓ Passed

- Advice** O/s/r and n/s/r brake pads low
- Advice** Offside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear discs rusty
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Power steering pipes damp

MOT #17 2020-10-07 10:20**MOT test number** 737429194479**Result** ✗ Failed

- Advice** Power steering pipes damp
- Advice** Offside Front Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** O/s/r and n/s/r brake pads low
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Both rear discs rusty

MOT #16 2019-10-02 13:57**MOT test number** 126818839318**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #15 2019-10-02 10:45

MOT test number 730861157886

Result ✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Headlamp light source and lamp not compatible (4.1.4 (c))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Fail Nearside Front Headlamp light source and lamp not compatible (4.1.4 (c))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14 2018-10-05 16:49

MOT test number 680151946512

Result ✓ Passed

Advice Both front tyres worn on edge

Advice Low reserve travel on park brake lever

Advice Bad oil leak on o/s of engine

Advice Plat in n/s/f lower arm front bush

**MOT #13**

2018-10-03 11:29

MOT test number

772049329951

Result**✗ Failed****Advice**

Low reserve travel on park brake lever

Advice

Bad oil leak on o/s of engine

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice

Plat in n/s/f lower arm front bush

Fail

Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

Fail

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Both front tyres worn on edge

MOT #12

2017-09-30 08:48

MOT test number

675659459550

Result**✓ Passed****Advice**

Oil leak on o/s of engine

Advice

Rear discs rusty

**MOT #11** 2017-09-27 10:55**MOT test number** 699011769390**Result** ✗ Failed**Fail** Offside Front Steering locking device missing Track rod end (2.2.C.1g)**Fail** Battery insecure (1.9.1)**Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)**Advice** Rear discs rusty**Fail** Offside Front Steering locking device missing Track rod end (2.2.C.1g)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Oil leak on o/s of engine**MOT #10** 2016-09-23 15:06**MOT test number** 620233966458**Result** ✓ Passed**MOT #9** 2015-09-25 10:22**MOT test number** 917988197375**Result** ✓ Passed**MOT #8** 2014-09-24 15:03**MOT test number** 389037064206**Result** ✓ Passed

**MOT #7** 2013-09-25 11:36**MOT test number** 267608263224**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2012-09-24 16:14**MOT test number** 346088262474**Result** ✓ Passed**MOT #5** 2011-09-26 10:19**MOT test number** 405269261272**Result** ✓ Passed**MOT #4** 2010-09-04 11:55**MOT test number** 163907640219**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)



MOT #3	2010-09-04 09:02
MOT test number	151427440295
Result	✗ Failed
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Notice	Offside headlamp dim.
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Fail	Nearside Inner Rear position lamp(s) not working (1.1.A.3b)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2009-09-12 11:22
MOT test number	471355359239
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-09-12 09:04
MOT test number	280025159275
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Steering retaining device missing (2.2.C.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Inner Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	OV56CHH
Plate since	2019-03-28
Current registration	OV56CHH
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-21
Last registration	2023-11-03
Complete history	See info



Registration #1	2006-09-21	20 mi
Registration #2	2009-09-12	60.231 mi
Registration #3	2009-09-12	60.231 mi
Registration #4	2010-09-04	89.488 mi
Registration #5	2010-09-04	89.488 mi
Registration #6	2011-09-26	97.531 mi
Registration #7	2012-09-24	108.232 mi
Registration #8	2013-09-25	121.874 mi
Registration #9	2014-09-24	135.257 mi
Registration #10	2015-09-25	147.914 mi
Registration #11	2016-09-23	157.752 mi
Registration #12	2017-09-27	162.172 mi
Registration #13	2018-09-28	162.172 mi
Registration #14	2019-09-28	162.172 mi
Registration #15	2020-09-28	162.172 mi
Registration #16	2021-09-28	162.172 mi
Registration #17	2022-09-28	162.172 mi
Registration #18	2023-09-28	162.172 mi
Registration #19	2023-09-28	162.172 mi
Registration #20	2023-09-28	162.172 mi
Registration #21	2023-09-28	162.172 mi
Registration #22	2023-09-28	162.172 mi
Registration #23	2023-09-28	162.172 mi
Registration #24	2023-09-28	162.172 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1477 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22A13000374