





report date: 2024-03-28

## General information

Make	MINI
Model	MINI (R60) ONE
Colour	White
Year of manufacture	2012
Top speed	107 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2022-05-02

Pictures 22

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-05-10
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #11	2024-04-17 11:54
MOT test number	726863262093
Result	✓ Passed
Next expiry date	2025-05-10
Advice Child Seat fitted not allowing full inspection of adult belt	

MOT #10	2023-05-11 10:58
MOT test number	364597624231
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #9	2022-04-19 08:48
MOT test number	848402320421
Result	✓ Passed

MOT #8	2021-05-10 11:54
MOT test number	480681072394
Result	<b>✓</b> Passed
Minor Windscreen damaged but not adversely affecting driver's view	small chip been repaired (3.2 (a) (i))

CarCheck.co.uk page 3/12



Advice

SV120KK

report date: 2024-03-28

MOT #7		2020-08-31 15:10
MOT test num	nber	535389958168
Result		✓ Passed
MOT #6		2019-08-31 09:24
MOT test num	nber	663301958571
Result		✓ Passed
MOT #5		2018-09-01 10:49
MOT test num	nber	431791138647
Result		✓ Passed
MOT #4		2017-09-04 16:41
MOT test num	nber	292396002333
Result		✓ Passed
MOT #3		2016-09-05 09:58
MOT test num	nber	629839492002
Result		✓ Passed
MOT #2		2016-03-05 10:51
MOT test num	nber	629688037195
Result		✓ Passed
<b>Advice</b> Of	fside Rear tyre outer side wall started to crack	
Advice Of	fside Front Tyre worn close to the legal limit and outer side wall started to	o crack (4.1 E.1)
	iside Front Tyre worn close to the legal little and outer side wall stafted to	U CIACK (4.1.E.1)
<b>Advice</b> Ne	earside Rear tyre outer side wall started to crack	

CarCheck.co.uk page 4/12

Nearside Front Tyre worn close to the legal limit and outer side wall started to crack (4.1.E.1)



SV120KK

report date: 2024-03-28

MOT #1 2015-03-07 10:46

**MOT test number** 677856865035 Result ✓ Passed Notice Engine covers fitted obscuring some components in the engine bay Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Notice All tyres cracking on side walls Notice Under-trays fitted obscuring some underside components Notice Play in steering rack inner joint(s) Notice All four tyre cracking/splitting on traeds

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	10 May 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



SV120KK

report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



SV120KK

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I	
*********	
***************************************	
*********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-07
Last registration	2024-04-17
Complete history	See info



Registration #1	2012-03-07	9 mi
Registration #2	2015-03-07	18.699 mi
Registration #3	2016-03-05	22.620 mi
Registration #4	2016-09-05	24.335 mi
Registration #5	2017-09-04	28.264 mi
Registration #6	2018-09-01	32.543 mi
Registration #7	2019-08-31	38.835 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

## Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine numberB409J297