





report date: 2024-03-29

## General information

| Make                | VAUXHALL           |
|---------------------|--------------------|
| Model               | ANTARA SE NAV CDTI |
| Colour              | Beige              |
| Year of manufacture | 2013               |
| Top speed           | 119 mph            |
| 0 - 60 mph          | 10.1 seconds       |
| Gearbox             | 6 speed automatic  |

## Engine & fuel consumption

| Power                   | 182 BHP             |
|-------------------------|---------------------|
| Max. torque             | 400 Nm at 2.000 rpm |
| <b>Engine capacity</b>  | 2.231 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 26.9 mpg            |
| Consumption extra urban | 44.1 mpg            |
| Consumption combined    | 35.8 mpg            |
| CO2 emission            | 208 g/km            |
| CO2 label               | K                   |



CarCheck.co.uk page 1/12




# Internet history

## Entry 1

Date 2022-02-16

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2024-08-17 |
|--------------------|------------|
| MOT pass rate      | 73 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 3          |
| Total advice items | 9          |
| Total items failed | 6          |

| MOT #11   | 2023-08-18 13:23 |
|---|------------------|
| MOT test number   | 126683222512     |
| Result  | ✓ Passed         |
| Next expiry date  | 2024-08-17       |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt |                  |

| MOT #10   | 2023-08-17 11:39 |
|---|------------------|
| MOT test number   | 637866760986     |
| Result  | <b>X</b> Failed  |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))      |                  |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt |                  |
| Fail Reversing lamp inoperative (4.6.1 (a))                                       |                  |
| Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))                 |                  |
| Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                   |                  |

| MOT #9   | 2022-04-13 15:57 |
|--|------------------|
| MOT test number  | 898562939535     |
| Result   | <b>✓</b> Passed  |
| Advice Parking brake efficiency just passed on 16%, would recommend adjustment |                  |

CarCheck.co.uk page 3/12



FV62KXK

report date: 2024-03-29

**MOT #8** 2021-08-09 13:47

776916173265 **MOT** test number

Result ✓ Passed

**Advice** 

Zero Emitter, No Smoke Readings available

**MOT #7** 2020-06-16 14:01

**MOT** test number 842449847367

Result ✓ Passed

**MOT #6** 2020-06-09 09:39

**MOT** test number 811667687185

Result × Failed

**Advice** Brake pipe corroded, covered in grease or other material Both front to rear (1.1.11 (c))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #5** 2019-06-07 15:46

**MOT** test number 727932682956

Result Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn bald inner edge (5.2.3 (e))

MOT #4 2019-06-07 15:22

**MOT** test number 974641090923

Result × Failed

Fail Nearside Rear Reversing lamp inoperative (4.6.1 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn bald inner edge (5.2.3 (e))

CarCheck.co.uk page 4/12



FV62KXK

report date: 2024-03-29

| MOT #3  | 2018-06-07 13:58 |
|---|------------------|
| MOT test number                                 | 372264304931     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #2  | 2017-05-31 13:59 |
| MOT test number                                 | 913259794195     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #1  | 2016-06-10 15:15 |
| MOT test number                                 | 865333182627     |
| Result  | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (3.5.1g) |                  |

CarCheck.co.uk page 5/12



### Tax & MOT check



| Tax status       | Valid until 1 October |
|------------------|-----------------------|
| Days left        | 154                   |
| MOT expiry date  | 17 August 2024        |
| Full MOT history | See MOT history       |

### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | K          |
| Single payment (12 months)              | £ 395,00,- |
| Single six month payment                | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. |             |
|--|-------------|
| *******  |             |
|  |             |
| ***************************************  |             |
|  |             |
|  |             |
| ***************************************  |             |
| Plate changes  | More info > |
| See in this check if this VAUXHALL had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   | UK NE       |
| Plate since  |             |
| Current registration   | OK SIES     |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 9/12



## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| 0.1.116           |  |

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 13         |
| First mileage registration | 2013-02-15 |
| Last registration          | 2023-08-18 |
| Complete history           | See info   |



| Registration #1  | 2013-02-15 | 22 mi     |
|------------------|------------|-----------|
| Registration #2  | 2016-06-10 | 39.605 mi |
| Registration #3  | 2017-05-31 | 65.873 mi |
| Registration #4  | 2018-06-07 | 74.285 mi |
| Registration #5  | 2019-06-07 | 90.999 mi |
| Registration #6  | 2019-06-07 | 90.999 mi |
| Registration #7  | 2020-06-09 | 99.486 mi |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 0.074     |

More info >

CarCheck.co.uk page 11/12



## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 95%             |
| Children       | 84%             |
| Pedestrian     | 46%             |
| Safety systems | 71%             |
| Overall rating | 81%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 2085 mm |
|---------------------|---------|
| Height              | 1717 mm |
| Length              | 4596 mm |
| Wheel base          | 2707 mm |
| Kerb weight         | 1921 kg |
| Max. allowed weight | 2505 kg |

## Additional information

| Fuel tank capacity | 65 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | 227236K          |

CarCheck.co.uk page 12/12