



PK58VRM

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	15.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	155 Nm at 1.600 rpm
Engine capacity	1.422 cc
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-14
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-04-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	37
Total items failed	13

MOT #18	2023-04-05 09:54
MOT test number	407329695575
Result	✓ Passed
Next expiry date	2024-04-29
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Sub-frame corroded but not seriously weakened rear axle (5.3.3 (b) (i))



MOT #17 2022-04-30 11:29

MOT test number 842835258713

Result ✓ Passed

- Advice** Rear rear exhaust outer casing loose
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear reversing light not working
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #16**

2022-04-22 09:10

MOT test number

281126390505

Result**✗ Failed**

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Rear reversing light not working
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Front Drive shaft securing bolt loose (6.1.7 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Direction indicator not working in mirror (4.4.1 (a) (ii))
- Advice** Rear rear exhaust outer casing loose
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

2020-09-11 14:57

MOT test number

503441063936

Result**✓ Passed**

**MOT #14**

2020-09-11 11:55

MOT test number

264637403041

Result

✗ Failed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Rear Coil spring fractured or broken dangerous (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm inside edge (5.2.3 (e))

MOT #13

2019-08-20 12:05

MOT test number

977378913075

Result

✓ Passed

- Advice** Handbrake travel high
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2018-10-08 14:29

MOT test number

416166555531

Result

✓ Passed

MOT #11

2017-11-25 09:41

MOT test number

566113877615

Result

✓ Passed

- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #10** 2017-11-24 10:15**MOT test number** 225159543767**Result** ✗ Failed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2016-11-24 13:25**MOT test number** 586489748672**Result** ✓ Passed**MOT #8** 2016-11-23 09:36**MOT test number** 206034241185**Result** ✗ Failed**Fail** Offside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #7** 2015-11-18 11:08**MOT test number** 982120473121**Result** ✓ Passed**MOT #6** 2014-11-20 10:19**MOT test number** 379384524335**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre out of shape

**MOT #5** 2013-11-23 09:37**MOT test number** 275837023357**Result** ✓ Passed**MOT #4** 2012-11-17 11:42**MOT test number** 776332022349**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #3** 2012-11-17 09:42**MOT test number** 556232822306**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2011-11-10 09:57**MOT test number** 436674111425**Result** ✓ Passed**MOT #1** 2011-11-10 09:57**MOT test number** 899854711356**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PK58VRM
Plate since	2024-03-29
Current registration	 PK58VRM
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-29
Last registration	2023-04-05
Complete history	See info



Registration #1	2008-11-29	19 mi
Registration #2	2011-11-10	25.259 mi
Registration #3	2012-11-17	34.161 mi
Registration #4	2012-11-17	34.161 mi
Registration #5	2013-11-23	40.692 mi
Registration #6	2014-11-20	49.054 mi
Registration #7	2015-11-18	53.018 mi
Registration #8	2016-11-23	60.024 mi
Registration #9	2016-11-24	60.024 mi
Registration #10	2017-11-24	69.687 mi
Registration #11	2018-11-29	75.259 mi
Registration #12	2019-11-29	80.831 mi
Registration #13	2020-11-29	86.403 mi
Registration #14	2021-11-29	91.975 mi
Registration #15	2022-11-29	97.547 mi
Registration #16	2023-11-29	103.119 mi
Registration #17	2024-11-29	108.691 mi
Registration #18	2025-11-29	114.263 mi
Registration #19	2026-11-29	119.835 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BNM317137