



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	63
Total items failed	9

MOT #16	2023-12-01 08:03
MOT test number	207395251516
Result	✓ Passed
Next expiry date	2024-12-06
Advice	Rear wiper blade defective
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside handbrake cable mount detached
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #15

2023-11-30 12:54

MOT test number

122821272928

Result		✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Nearside handbrake cable mount detached	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Rear wiper blade defective	

**MOT #14**

2022-12-07 08:53

MOT test number

726438713254

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear wiper blade defective
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside handbrake cable bracket corroded
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #13

2021-12-07 14:33

MOT test number

865536679199

Result

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside handbrake cable bracket corroded
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2020-11-24 15:36

MOT test number

932938214517

Result

✓ Passed

- Advice** Coolant leak.
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface.
(1.1.14 (a) (ii))
- Advice** Rear exhaust corroded and clamp missing.
- Advice** Brake fluid slightly low.
- Advice** Rear axle corroded.
- Advice** Battery secured with packing piece.

MOT #11

2020-11-24 12:14

MOT test number

539240812606

Result

✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Battery secured with packing piece.
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Coolant leak.
- Advice** Rear exhaust corroded and clamp missing.
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface.
(1.1.14 (a) (ii))
- Advice** Brake fluid slightly low.
- Advice** Rear axle corroded.

**MOT #10** 2019-06-04 15:42**MOT test number** 737463412315**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust silencer slightly loose clamp missing at rear section (8.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-06-04 15:29**MOT test number** 962553957487**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust silencer slightly loose clamp missing at rear section (8.1.1 (b) (i))**MOT #8** 2018-05-31 11:27**MOT test number** 582887255569**Result** ✓ Passed**Advice** Front tyres starting to get low**Advice** Rear exhaust box outer rusty**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #7** 2017-06-07 11:38**MOT test number** 862582063235**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit just legal (4.1.E.1)**Advice** Rear silencer deteriorating in general**Advice** Items removed from driver's view prior to test**MOT #6** 2017-06-07 11:38**MOT test number** 550947708359**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit just legal (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Items removed from driver's view prior to test**Advice** Rear silencer deteriorating in general**MOT #5** 2016-05-26 13:14**MOT test number** 239661363012**Result** ✓ Passed**Advice** Slight bind developing n/s/r brake, will require attention soon**Advice** Minor deterioration developing rear silencer**MOT #4** 2015-05-20 16:19**MOT test number** 118630745102**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2015-05-20 11:46
MOT test number	168620245141
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Notice	Items removed from driver's view prior to test
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2014-03-10 15:15
MOT test number	186299464418
Result	✓ Passed
MOT #1	2013-03-08 13:28
MOT test number	905247863079
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-30
Last registration	2023-12-01
Complete history	See info



Registration #1	2010-07-30	28 mi
Registration #2	2013-03-08	28.538 mi
Registration #3	2014-03-10	33.109 mi
Registration #4	2015-05-20	43.786 mi
Registration #5	2015-05-20	43.786 mi
Registration #6	2016-05-26	49.137 mi
Registration #7	2017-06-07	52.323 mi
Registration #8	2017-06-07	52.323 mi
Registration #9	2018-05-31	57.671 mi
Registration #10	2019-05-20	58.377 mi
Registration #11	2019-05-20	58.377 mi
Registration #12	2019-05-20	58.377 mi
Registration #13	2019-05-20	58.377 mi
Registration #14	2019-05-20	58.377 mi
Registration #15	2019-05-20	58.377 mi
Registration #16	2019-05-20	58.377 mi
Registration #17	2019-05-20	58.377 mi
Registration #18	2019-05-20	58.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203