





General information

Make	MINI
Model	COOPER CLUBMAN
Colour	White
Year of manufacture	2010
Top speed	125 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry	1

Date Pictures 2021-06-23

12

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	6

MOT #14	2023-06-23 14:17
MOT test number	933450742681
Result	✓ Passed
Next expiry date	2024-06-28

MOT #13	2023-06-23 11:05
MOT test number	999734630365
Result	🗙 Failed
Fail Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Minor Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Fail Nearside Position lamp not working (4.2.1 (a) (ii))	



GV10KPT report date: 2024-03-28

MOT #12		2022-06-24 12:19
MOT test	number	416074059880
Result		✓ Passed
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))

MOT #11	2021-06-29 12:01
MOT test number	748675297274
Result	✓ Passed

MOT #10	2020-11-13 09:49
MOT test n	umber 861946873644
Result	✓ Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #92019-05-03 10:18MOT test number206556341897Result✓ PassedAdviceNearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceUnder trays fittedAdviceOffside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #8		2019-05-02 13:05
MOT test	number	705782266166
Result		🗙 Failed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail 0	ffside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Under trays fitted	

MOT #7	2018-03-31 14:52
MOT test number	648076749919
Result	✓ Passed
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #6	2018-03-31 14:52
MOT test number	825171460297
Result	× Failed
Advice Offside Front She	ock absorber has a light misting of oil (2.7.3)
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5	2017-03-18 11:49
MOT test number	614766151889
Result	✓ Passed
МОТ #4	2016-03-15 07:02
MOT test number	825185257346

✓ Passed





MOT #3	2015-06-22 11:10
MOT test number	959403575193
Result	✓ Passed
MOT #2	2014-06-24 10:21
MOT test number	816595074162
Result	✓ Passed
MOT #1	2013-06-21 12:43
MOT test number	765582073191
Result	✓ Passed



GV10KPT report date: 2024-03-28

Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 28 June 2024
Tax status	Valid until 1 July
Days left	64
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



GV10KPT report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-23
Last registration	2023-06-23
Complete history	See info



Registration #1	2010-06-23	8 mi
Registration #2	2013-06-21	41.906 mi
Registration #3	2014-06-24	45.870 mi
Registration #4	2015-06-22	55.471 mi
Registration #5	2016-03-15	61.363 mi
Registration #6	2017-03-18	67.294 mi
Registration #7	2018-03-31	73.612 mi
Registration #8	2018-03-31	73.612 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.117 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1913 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1145 kg
Max. allowed weight	1645 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Engine number

A442I730