





report date: 2024-03-29

General information

| Make | TOYOTA |
|---------------------|------------------------|
| Model | COROLLA VERSO VVT-I SR |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 121 mph |
| 0 - 60 mph | 12.7 seconds |
| Gearbox | 5 speed Semi-Automatic |

Engine & fuel consumption

| Power | 127 BHP |
|-------------------------|---------------------|
| Max. torque | 170 Nm at 4.200 rpm |
| Engine capacity | 1.794 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.1 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 179 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-11-28

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

| Date | 2021-06-11 | |
|------|------------|--|
|------|------------|--|

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-07-26 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 4 |

| MOT #15 | 2023-07-27 15:20 |
|------------------------------------|------------------|
| MOT test number | 654627504986 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-26 |
| Advice Nearside Front Nail in tyre | |

| MOT #14 | 2023-07-27 12:23 |
|---|---------------------------|
| MOT test number | 170869171172 |
| Result | X Failed |
| Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i)) | light sources (4.7.1 (b) |
| Advice Nearside Front Nail in tyre | |
| Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning h | igh stop light (4.3.1 (a) |

| MOT #13 | 2022-05-19 10:39 |
|---|------------------|
| MOT test number | 974350644608 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/12



MOT #8

Result

GR08FHP

report date: 2024-03-29

2018-01-24 08:44

X Failed

MOT #12 2021-01-12 14:27 **MOT test number** 594202370286 Result ✓ Passed MOT #11 2020-01-08 10:31 **MOT** test number 113908251752 Result ✓ Passed MOT #10 2020-01-08 10:31 **MOT test number** 104326515276 Result × Failed **Pass with rectification** Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

| MOT #9 | 2019-01-23 12:37 |
|---|------------------|
| MOT test number | 402554667296 |
| Result | ✓ Passed |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| 1101 110 | 2010 01 21 00.11 |
|-----------------|------------------|
| MOT test number | 318051986953 |
| Result | ✓ Passed |
| MOT #7 | 2018-01-24 08:44 |
| MOT test number | 224927812487 |

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #5
 2016-01-21 12:21

 MOT test number
 536815134325

 Result
 ✓ Passed

 MOT #4
 2014-12-19 11:24

 MOT test number
 326663154345

 Result
 ✓ Passed

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

135777542379

Result

Notice Nail in rear tyre

MOT #1

MOT test number

Result

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 366 |
| MOT expiry date | 26 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | T |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

GR08FHP

report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. ober of plates

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2008-07-31 |
| Last registration | 2023-07-27 |
| Complete history | See info |



| Registration #1 | 2008-07-31 | 16 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-01-04 | 23.877 mi |
| Registration #3 | 2012-12-12 | 29.962 mi |
| Registration #4 | 2013-12-19 | 36.465 mi |
| Registration #5 | 2014-12-19 | 44.222 mi |
| Registration #6 | 2016-01-21 | 50.284 mi |
| Registration #7 | 2017-01-13 | 52.972 mi |
| Registration #8 | 2018-01-24 | 57.470 mi |
| Registration #9 | 2018-01-24 | 57.470 mi |
| Registration #10 | | 71.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 71.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 9.70 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 60295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1620 mm |
| Length | 4360 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1365 kg |
| Max. allowed weight | 2035 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 12/12 |

Number of axles 2

Engine number 1ZZV011339